

ANNUAL SURVEYS.

39988

No. 39988 Survey held at London Date, first Survey and Last Survey 6th Jan^y 1881
 No. in on the Sch^r "Viking" Master - Stevens
 Reg. Book. 2414 Tonnage 114 Built at Peterhead When built 1873 10th mo
 By whom built Stephen Owners A. Bain
 Port belonging to Wick Destined Voyage Newcastle
 If Surveyed Afloat or in Dry Dock Afloat in Surrey Commercial Dock

Last Survey, No. 14393 Port of Wick Classed 9 A 1
 Present Condition of the
 Decks Good Treenails Good N. J. Pet. 79 6. 79
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places Not seen
 Planksheers " Keelsons Good
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter Not seen Copper or Y.M. " When put on "
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways Good
 Coal Bunker, Openings, Lids, &c. " Scuppers " Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c.

This vessel was examined afloat, with a clear hold, as far as could be seen, she is in good condition and eligible, in my opinion, to continue as classed

Committee's Minute Friday, January 14th. 1881. James Surpin
 Character assigned 9 A 1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid 18

No. 3141 Survey held at London Date, first Survey and Last Survey 6th Jan^y 1881
 No. in on the Sch^r "Lily" Master H. Smith
 Reg. Book. 1441 Tonnage 40 Built at Portray When built 1878 9th mo
 By whom built Smith Owners H. Smith
 Port belonging to Bonff Destined Voyage Coasting
 If Surveyed Afloat or in Dry Dock Afloat in Surrey Commercial Dock

Last Survey, No. 3141 Port of Abn Classed 9 A 1
 Present Condition of the
 Decks Good Treenails Good 9. 78
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places Not seen
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter Not seen Copper or Y.M. " When put on "
 Engine Room Skylights " Caulking of Bottom, Deck, & Waterways Good
 Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c.

This vessel was examined afloat while discharging a cargo of wheat, she was in good condition as far as could be seen, and eligible, in my opinion, to continue as classed

Committee's Minute Friday, January 14th. 1881. James Surpin
 Character assigned 9 A 1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) " Paid 18