

ANNUAL SURVEYS.

Tuesday January, 11th. 81.
(Received at London Office, 40002)

No. 40,002 Survey held at London Date, first Survey and Last Survey 4th Jan^y 1881
No. in on the S. S. "Phone" Master J. Westcott
Reg. Book. 301 Tonnage 1343 Built at Sunderland When built 1868 2 mo.
By whom built Pile Owners Westcott & Laurence
Port belonging to London Destined Voyage Odessa
If Surveyed Afloat or in Dry Dock Carter's Dry Dock

Last Survey, No. 26333 Port of Irre Classed 90 A 1
nt Condition of the Good Pivots Good S. S. Lon. No 2. 79 - 4.80

Waterways	Good	Treenails	Good	Windlass and Capstan	Good
Comings	Good	Breasthooks and Stemson	Good	Pumps	4 in No 2
Upper Deck Beams & Fastenings	Good	Transoms, Pointers, and Crutches	Good	Boats	4 in No 2
Lower Deck Beams & Fastenings	Good	Timbers of the Frame at the Openings	Good	Masts, Yards, &c.	Good
Planksheers	Good	Ditto ditto at other places	Good	Condition, how ascertained	from D.K.
Sheerstrakes	Plating	Keelsons	Good	Sails	Sufficient & Good
Topsides	Good	Clamps and Shelves	Good	Anchors, No. of	3 B. 1 S. 2 K.
Wales	Good	Ceiling	Good	Cables	Complete & Good
Plank (Bottom) and Counter	Good	Rudder	Good	Hawsers and Warps	5 in No
Engine Room Skylights	Good	Copper or Y.M. Coating When put on	Good	Standing and Running Rigging	Good
Coal Bunker, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	Good	Cargo and Main Hatchways	Good
General Observations, Opinion as to Class, &c.					

The Close Ceiling on Tops of all Masts, has been removed and the tops coated with Tar and Cement; the After Hatch beams in Lower hold have been straightened; and she has had a new Fore Topmast. The bottom has been cleaned & coated, she is in good condition, and eligible, in my opinion, to continue as classed

Committee's Minute Tuesday January, 18th. 1881. James Purkin
Character assigned GOOD Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Tonnage Built at When built
By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed
Present Condition of the
Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18