

ANNUAL SURVEYS.

No. 40004 Survey held at London Date, first Survey 8th Jan Last Survey 12th Jan 1881
 No. in on the Iron Bk "Proville" Master H. Davies
 Reg. Book 1326 Tonnage 524.524.507 Built at Liverpool When built 1865-18 mo
 By whom built Evans Owners J. Gambles
 Port belonging to Liverpool Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Ratcliffe & D^o

Last Survey, No. 4923 Port of Iron Classed SS Lws 3.77
 Present Condition of the
 Decks Good Trunnails Rivets Good
 Waterways --- Breasthooks and Stemson ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- ~~Timbers~~ of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- ~~Ditto~~ ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder ---
~~Plank~~ (Bottom) and Counter --- ~~Copper or V.M.~~ Cement When put on 1865
 Engine Room Skylights --- Coal Bunker, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom repainted. one new Rudder pintle and brace
other pintles bushed. She is now in good condition and in my
opinion may continue as Classed

Committee's Minute Tuesday January, 18th. 1881. W. L. C. Davey
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18

No. 77 Survey held at London Date, first Survey 2nd Dec Last Survey 13th Dec 1880
 No. in on the Iron S. "Lady Elizabeth" Master Finlay
 Reg. Book 77 Tonnage 155.1208.1091 Built at Sunderland When built 1879. 6 mo
 By whom built Thompson & Co Owners J. Wilson
 Port belonging to London Destined Voyage ---
 If Surveyed Afloat or in Dry Dock Princes dry Dk

Last Survey, No. 23946 Port of Iron Classed 100A 1
 Present Condition of the
 Decks Good Trunnails Rivets Good
 Waterways --- Breasthooks and Stemson ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- ~~Timbers~~ of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- ~~Ditto~~ ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder ---
~~Plank~~ (Bottom) and Counter --- ~~Copper or V.M.~~ Cement When put on 1879
 Engine Room Skylights --- Coal Bunkers, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom painted, also upper works. She is now
in good condition and in my opinion eligible to continue
as Classed

Committee's Minute Tuesday January, 18th. 1881. W. L. C. Davey
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) --- Paid --- 18