

ANNUAL SURVEYS.

40014

No. 40, 014 Survey held at London Date, first Survey 14 Jan Last Survey 15 Jan 1881
 No. in on the 253 Reg. Book. Tonnage 1357 Built at Port Glasgow Master R. Serrat
 By whom built Murray Owners D. Law
 Port belonging to Glasgow Destined Voyage Algera Bay
 If Surveyed Afloat or in Dry Dock Limehouse Dry Dock

Last Survey, No. 4603 Port of London Years assigned. 100 A 1 Character in Register Book. 9.79

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>		Pumps <u>4 in No 2</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>		Boats <u>4 in No 2</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>		Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>		Condition, how ascertained <u>by enquiry</u>
Planksheers <u>"</u>	Keelsons <u>"</u>		Sails <u>2 cuts and Good</u>
Sheerstrakes <u>Plating</u>	Clamps and Shelves <u>"</u>		Anchors, No. of <u>3 B. 1 S. 2 H.</u>
Topsides <u>"</u>	Ceiling <u>"</u>		Cables <u>Complete and Good</u>
Wales <u>"</u>	Rudder <u>"</u>		Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Coating</u> When put on <u>now</u>		Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>"</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>		Cargo and Main Hatchways <u>Good</u>
Coal Bunker, Openings, Lids, &c. <u>"</u>	Scuppers <u>"</u>		Hatches <u>"</u>

General Observations, Opinion as to Class, &c.
A new main upper Trossil yard has been supplied of P.P. The bottom has been cleaned & coated, she is in good condition and eligible, in my opinion to continue as classed

Committee's Minute Friday, January 24th. 18 81.
 Character assigned 100 A 1
 Surveyor James Surpin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 1881

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Reg. Book. Tonnage _____ Built at _____ Master _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Years assigned. _____ Character in Register Book. _____

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18____

