

ANNUAL SURVEYS.

40,020

(Received at London Office, 11th January 1881)

Survey held at London Date, first Survey 4 Jan 79 Last Survey 6 Jan 79 1881

No. in Reg. Book. on the SS. "Monaco" Master B Cole

Tonnage 405.674.578 Built at S Shields When built 1875-10 mo

By whom built Readhead Owners P. Dansey & Robinson

Port belonging to S Shields Destined Voyage Lardiff

If Surveyed Afloat or in Dry Dock Mountain Green

Last Survey, No. 6740 Port of Tuan Years assigned. 100A1 12-79 Character in Register Book.

Condition of the Good Classed S.S. La ho 2-79

Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>---</u>	Breasthooks and Stemson	<u>---</u>	Pumps	<u>---</u>
Comings	<u>---</u>	Transoms, Pointers, and Crutches	<u>---</u>	Boats <u>3rs</u>	<u>---</u>
Upper Deck Beams & Fastenings	<u>---</u>	Timbers of the Frame at the Openings	<u>---</u>	Masts, Yards, &c.	<u>---</u>
Lower Deck Beams & Fastenings	<u>---</u>	Timbers ditto at other places	<u>---</u>	Condition, how ascertained	<u>from deck</u>
Planksheers	<u>---</u>	Keelsons	<u>---</u>	Sails	<u>Good</u>
Sheerstrakes	<u>---</u>	Clamps and Shelves	<u>---</u>	Anchors, No. of <u>3 B. 18 + 2 K</u>	<u>Good</u>
Topsides	<u>---</u>	Ceiling	<u>---</u>	Cables	<u>Good</u>
Wales	<u>---</u>	Rudder	<u>---</u>	Hawsers and Warps <u>3rs</u>	<u>---</u>
Plank (Bottom) and Counter	<u>---</u>	Copper or Y.M. <u>Cement</u> When put on <u>1875</u>	<u>---</u>	Standing and Running Rigging	<u>---</u>
Engine Room Skylights <u>Good</u>	Coal Bunker, Openings, Lids, &c. <u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways <u>Good</u>	Hatches <u>Good</u>

General Observations, Opinion as to Class, &c.

Rudder pintles bucked. bottom coated. inside painted. she is now in good condition and in my opinion may continue as classed

Committee's Minute Tuesday January, 25th. 1881.

Character assigned 100A1 JRM

Wm B. Dansey
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

No. on the Reg. Book. 0. Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____

Master _____

Tonnage _____ Built at _____ When built _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Years assigned. _____ Character in Register Book.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. _____ When put on _____	Standing and Running Rigging
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18 _____

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) Paid 18

