

ANNUAL SURVEYS.

140,025

No. _____ Survey held at London Date, first Survey and Last Survey 17th Jan 1881
 (Received at London Office, 27th Jan 1881)
 No. in on the Iron S.S. "Ardenhan" Master Couth
 Reg. Book. 29 Tonnage 923 Built at Port Glasgow When built 1880
741 By whom built Murray Owners Melaren, Crum & Co.
 Port belonging to Glasgow Destined Voyage Port Glasgow
 If Surveyed Afloat or in Dry Dock Commercial Dry Dock.

Last Survey, No. 27459 Port of London Classed 100 A 1
 Years assigned. _____ Character in Register Book. P. 80
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes Plating _____ Clamps and Shelves _____
 Topsides _____ Rudder _____
 Wales _____ Copper or Y.M. Coating When put on Now
 Plank (Bottom) and Counter _____ Caulking of _____
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers _____ Cargo and Main Hatchways Good Hatches _____
 General Observations, Opinion as to Class, &c. _____

The bottom has been cleaned and coated, she is in good condition and eligible, in my opinion, to continue as classed.

Committee's Minute Tuesday January 25th 1881
 Character assigned 100 A 1
J. Purkin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. _____ Character in Register Book. _____
 Present Condition of the
 Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Rudder _____
 Wales _____ Copper or Y.M. _____ When put on _____
 Plank (Bottom) and Counter _____ Caulking of _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

