

ANNUAL SURVEYS.

40031

No. 40031 Survey held at London Date, first Survey Dec 31/80 Last Survey Jan 17th 1881
 No. in on the SS Dunrobin Castle Master J Lawson
 Reg. Book. 548 Tonnage { Net 1784 Built at Glasgow When built 1875 Year. 11 Month. 11
 { Gross 2811 By whom built Napier Owners J Currie & Co
 { Under Dk. 2737 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greens Bay St
 (State Name of Dock.)

Last Survey, No. 39074 Port of London Classed 100A 7.80
 Present Condition of the Decks good Treenails Circle good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From St
 Topsides " Ceiling " Sails good
 Wales " Rudder " Anchors, No. of 3 No. St & Reddy
 Plank (Bottom) and Counter " Copper or Y.M. London When put on Nov Cables Pool on St good
 Caulking of Bottom, Deck, & Waterways good Hawfers and Warps "
 Standing and Running Rigging "
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Bottom & cordage She is now in an efficient state and eligible to remain as classed, and when fees are paid she will be entitled to be recorded in the Register Book SS London No 1-1880. being specially surveyed last year

Committee's Minute Friday, January 28th. 1881. Senhouse Martindale
 Character assigned 100A 1 TBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage { Net _____ Built at _____ When built _____
 { Gross _____ By whom built _____ Owners _____
 { Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
 (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stenson _____
 Comings _____ Transoms, Pointers, and Crutches _____ Windlass and Capstan _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Pumps _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Boats _____
 Planksheers _____ Keelsons _____ Masts, Yards, &c. _____
 Sheerstrakes _____ Clamps and Shelves _____ Condition, how ascertained _____
 Topsides _____ Ceiling _____ Sails _____
 Wales _____ Rudder _____ Anchors, No. of _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Cables _____
 Caulking of Bottom, Deck, & Waterways _____ Hawfers and Warps _____
 Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



LON665-0073