

(40059)
Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 2-81)
No. in Reg. Book. Survey held at London Date, first Survey Jan 31 Last Survey Nov 1881
118 on the Machinery of the S.S. "Indus" (Number of Visits 1)
Tonnage, Gross 1907 Built at Newcastle When built 1877
Ditto, Net 1236 Owners Mercantile S S Co Ltd Port belonging to London
Diameter of Cylinder 32 x 62 Engines made by Black Hawthorn & Co When made 1877
Length of Stroke 36 Boilers made by Ditto When made 1877
Pressure of Steam 65 lbs If Surveyed Afloat or in Dry Dock Dry Dock Years assigned 100 A1
Registered Horse Power 200 Character in Register Book Lloyd's M.C. 12-77
Last Survey No. _____ Port _____ h-80

Particulars of Repairs and Examination for Annual Survey
Vessel placed in dry dock, sea connection
examined & found in good condition. Propeller and its
connection also satisfactory, the tail shaft being a good
fit in the stern gland.


General Observations, Opinion, and Recommendation:— The Machinery as far as
seen is in a safe working condition and eligible in my opinion
to remain as Classed.

Entry or Registering Fee ... £ : :
Survey Fee ... £ : : received by me,
Certificate (if required) ... £ : : 188
(Travelling Expenses, if any, £)

Committee's Minute Tuesday February 188

Assigned

Geo. A. Milner
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

LON 666-0111

It is submitted that this
vessel is eligible to
remain as chartered

JM
7/2/81



© 2021

Lloyd's Register
Foundation