

ANNUAL SURVEYS.

40,060

No. Survey held at London Date, first Survey Jan 17 Last Survey Feb 1st 1881
 No. in on the SS Taymouth Castle Master J. Fulton
 Reg. Book. 96 Net 1172 Built at Glasgow When built 1877 Year. 5 Month.
 Tonnage Gross 1827 Under Dk. 1780 By whom built Barclay Owners J. Currie & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Thames Lun Wks by St
 (State Name of Dock.)

Last Survey, No. 28135 Port of Iron

Classed 100 A/ 4-80 Years assigned. Character in Register Book.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Copper When put on Now
 Caulking of
 Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c. Bottom &c continue.

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday February 8th 1881

Character assigned 100 A/ 1

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of

Classed Years assigned. Character in Register Book.

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of
 Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18