

ANNUAL SURVEYS.

40094.

(Received at London Office, 19. 2. 81)

No. 40094 Survey held at London Date, first Survey Jan 13th Last Survey Feb 15th 1881
 No. in on the S Invercargill Master Muir
 Reg. Book. 1246 Built at Port Glasgow When built 1874-6
151 Tonnage 1310 Owners Albion Ship Co
 By whom built Greenan
 Port belonging to Glasgow Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 46227 Port of Iron Classed 100A-4.80
 Years assigned. 55 Cl. No. 1. 78.
 Character in Register Book.
 Present Condition of the Decks good
 Treenails Rivets good
 Breasthooks and Stemson good
 Transoms, Pointers, and Crutches good
 Timbers of the Frame at the Openings good
 Ditto ditto at other places good
 Keelsons good
 Clamps and Shelves good
 Ceiling good
 Rudder good
 Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps good
 Boats good
 Masts, Yards, &c. good
 Condition, how ascertained From S/C
 Sails good
 Anchors, No. of 3 Nos. 11-8 Redgs
 Cables Part on S/C good
 Hawasers and Warps good
 Standing and Running Rigging good
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom &c coated.

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday February 22nd 1881 Senhouse Martindale
 Character assigned 100A JTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. 46534 Survey held at London Date, first Survey Jan 7th Last Survey Jan 21st 1881
 No. in on the SS Jane Porter Master J Legg
 Reg. Book. 953 Built at Belfast When built 1860. 5
173 Tonnage 953 Owners J O Barry & Co
 By whom built Harland
 Port belonging to Belfast Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Greens Dock & afloat

Last Survey, No. 46534 Port of Iron Classed A1 5.80
 Years assigned. 55 Cl. No. 1. 78
 Character in Register Book. S.P. No 3-73
 Present Condition of the Decks good
 Treenails Rivets good
 Breasthooks and Stemson good
 Transoms, Pointers, and Crutches good
 Timbers of the Frame at the Openings good
 Ditto ditto at other places good
 Keelsons good
 Clamps and Shelves good
 Ceiling good
 Rudder Bushed
 Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps good
 Boats good
 Masts, Yards, &c. good
 Condition, how ascertained From S/C
 Sails good
 Anchors, No. of 3 Nos. 11-8 Redgs
 Cables Part on S/C good
 Hawasers and Warps good
 Standing and Running Rigging good
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom &c coated.

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday February 22nd 1881 Senhouse Martindale
 Character assigned 100A JTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

