

ANNUAL SURVEYS.

40,126

No. Survey held at London Date, first Survey July 14 Last Survey July 23^d 1881
 No. in on the SS Melviston Master
 Reg. Book. 474 Net 1136 Built at Hartholme When built 1875 Month. 10
 Tonnage Gross 1758 By whom built Graz Owners W Hartholme & Co
 Under Dk. 1387 Port belonging to London Destined Voyage Kurrachee
 If Surveyed Afloat or in Dry Dock Blackwall Pt Dry Dock
 (State Name of Dock.)

Last Survey, No. 2628 Port of Irish Classed 100 A. S. 80
 Present Condition of the
 Decks Good Treenails Drift Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery No)
 General Observations, Opinion as to Class, &c. Bottom & coated

She is now in an efficient state and eligible to remain as classed

Committee's Minute Tuesday March 1st, 1881
 Character assigned 100 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)
 Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid



© 2021

Lloyd's Register
Foundation