

ANNUAL SURVEYS.

40157

No. 207 Survey held at London Date, first Survey 7th Feb^y Last Survey 24th Feb^y 1881
 on the Iron S. Fiji. Master T. Brown.
 Reg. Book. 207 Net 1357 Built at Belfast When built 1875 9th Month.
 Tonnage Gross 1436 By whom built Harland Owners W. J. Myers, Son & Co
 Under Dk. 1299 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock In West India Dry Dock.
 (State Name of Dock.)

Last Survey, No. 2594 Port of Iran Classed L.S. Hul. N°1-P0 Character in Register Book. 100A.1.
 Years assigned. 3.80

Present Condition of the
 Decks good Treenails rivets good
 Waterways D° Breasthooks and Stemson D°
 Comings D° Transoms, Pointers, and Crutches D°
 Upper Deck Beams & Fastenings D° Timbers of the Frames at the Openings D°
 Lower Deck Beams & Fastenings D° Ditto ditto at other places D°
 Planksheers D° Keelsons D°
 Sheerstrakes D° Clamps and Shelves D°
 Topsides D° Ceiling D°
 Rudder D°
 Copper or V.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps D°
 Boats D°
 Masts, Yards, &c. D°
 Condition, how ascertained from the deck
 Sails good
 Anchors, No. of 3 B. 1 S. 2 K.
 Cables complete
 Hawser and Warps sufficient
 Standing and Running Rigging good

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good

(If a Steam Ship, state if a Report is also sent on the Machinery.....)
 General Observations, Opinion as to Class, &c.

The bottom has been examined, cleaned and coated.
 Vessel surveyed with part outward cargo in the hold amidships.
 She appears to be eligible to remain as classed.

Committee's Minute Friday, March. 11th. 1881. J. H. Truscott.

Character assigned 100A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 24 Survey held at London Date, first Survey 19th Feb^y Last Survey 7th March 1881
 on the Iron S. "Salamis." Master W. Philip.
 Reg. Book. 24 Net 1079 Built at Aberdeen When built 1875 5th Month.
 Tonnage Gross 1130 By whom built Hood. Owners W. Henderson
 Under Dk. 1021 Port belonging to Aberdeen. Destined Voyage not known
 If Surveyed Afloat or in Dry Dock In the Canal Dry Dock
 (State Name of Dock.)

Last Survey, No. 25393 Port of Iran Classed L.S. Mel. N°1-79. Character in Register Book. 100A.1
 Years assigned. 10.79.

Present Condition of the
 Decks good Treenails rivets good
 Waterways D° Breasthooks and Stemson D°
 Comings D° Transoms, Pointers, and Crutches D°
 Upper Deck Beams & Fastenings D° Timbers of the Frames at the Openings D°
 Lower Deck Beams & Fastenings D° Ditto ditto at other places D°
 Planksheers D° Keelsons D°
 Sheerstrakes D° Clamps and Shelves D°
 Topsides D° Ceiling D°
 Rudder D°
 Copper or V.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps D°
 Boats D°
 Masts, Yards, &c. D°
 Condition, how ascertained from the deck
 Sails good
 Anchors, No. of 3 B. 1 S. 2 K.
 Cables complete
 Hawser and Warps sufficient
 Standing and Running Rigging good

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good

(If a Steam Ship, state if a Report is also sent on the Machinery.....)
 General Observations, Opinion as to Class, &c.

The bottom has been examined, cleaned and coated.
 Vessel surveyed with ballast in the hold from the fore mast to the main mast.
 She appears to be eligible to remain as classed.

Committee's Minute Friday, March. 11th. 1881. J. H. Truscott.

Character assigned 100A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18