

REPORT of SURVEY for REPAIRS, &c.

40,180

No. 1186 on the S. "Profusilite" (Received at London Office, 16.3.81)
 No. in Survey held at London Date, first Survey 3rd Mar Last Survey 11th Mar 1881
 Reg. Book. 1186 on the S. "Profusilite" Master R. Heightholm
 Tonnage under Tonnage Deck 922 Built at Grays When built 1864 9
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1054 Owners J. Allau & Co Port belonging to London
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 1013 Residence
 Engine Room By whom built Stephen Destined Voyage Madras
 Reg. Tons as St' mer, cut on Bm. If Surveyed Afloat or in Dry Dock Limekiln dry Dk
(State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Years assigned. 20 A 1 4.80
 Character in Register Book. SS L 80
 Last Survey, No. 39084 Port London HT L 75
 REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Yellow metal stripped off, caulked from keel to metal line and the bottom remetalled in felt

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>—</u>	Breasthooks and Stenson	<u>—</u>	Pumps	<u>2 No</u>
Comings	<u>—</u>	Transoms, Pointers, and Crutches	<u>—</u>	Boats	<u>4 No</u>
Upper Deck Beams & Fastenings	<u>—</u>	Timbers of the Frame at the openings	<u>—</u>	Masts, Yards, &c.	<u>—</u>
Lower Deck Beams & Fastenings	<u>—</u>	Ditto Ditto at other places	<u>—</u>	Condition, how ascertained	<u>from Deck</u>
Planksheers	<u>—</u>	Keelsons	<u>—</u>	Sails	<u>Good</u>
Sheerstrakes	<u>—</u>	Clamps and Shelves	<u>—</u>	Anchors	<u>No. of 3 B. 18 + 2 No</u>
Topsides	<u>—</u>	Ceiling	<u>—</u>	Cables	<u>part seen</u>
Wales	<u>—</u>	Rudder	<u>—</u>	Hawsers and Warps	<u>3 No</u>
Plank (Bottom) and Counter	<u>—</u>	Copper <u>W.M. S.T.M.</u> When put on <u>1887</u>	<u>Good</u>	Standing & Running Riggers	<u>—</u>
Engine Room Skylights	<u>—</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>—</u>	Scuppers	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c.
She is now in good condition and in my opinion eligible to continue as classed

The Amount of Entry Fee ... £ 2 : 2 received by me, W. B. Savoy
 17/3/81 Special ... £ 2 : 2 18/3/81
 Certificate (if required) to be sent as per margin... £ 5

(Travelling Expenses, if any, £)
 Committee's Minute Friday, March 18th 1881
 Character assigned 20 A 1 4.80
 W. B. Savoy
 Surveyor to Lloyd's Register of British and Foreign Shipping.

The Surveys are requested not to write on or below the space for Committee's Minutes.

Insert Character precisely as in Register Book.

