

ANNUAL SURVEYS.

No. 443 Survey held at London Date, first Survey July 18th Last Survey March 24 1881
 No. in on the S Windsor Castle Master J Smith
 Reg. Book. 443 Tonnage 1075 Built at Sunderland When built 1857
 By whom built Green Owners R V & Green
 Port belonging to London Destined Voyage Bristol
 If Surveyed Afloat or in Dry Dock Green by Mr J. A. Green

Last Survey, No. 3 9108 Port of Lon Classed 140A-4.80

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>New Main Yard &c</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>From St</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Deerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>5 No. 12 & 14 lb</u>
Sides <u>"</u>	Ceiling <u>"</u>	Cables <u>Cast on side</u>
Planks <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Y Metal</u> When put on <u>1879</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>"</u>	Caulking of <u>Patched & resorted</u>	Cargo and Main Hatchways <u>Good</u>
General Observations, Opinion as to Class, &c. <u>"</u>	Bottom, Deck, & Waterways <u>new for</u>	Hatches <u>"</u>

She is now in an efficient state and eligible to remain as classed.

Committee's Minute

Tuesday March, 20th 1881.

Character assigned

Class 13 A

Senhouse Macindoe

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

No. 443 Survey held at London Date, first Survey July 18th Last Survey March 24 1881

No. in on the S Windsor Castle Master J Smith

Reg. Book. 443 Tonnage 1075 Built at Sunderland When built 1857

By whom built Green Owners R V & Green

Port belonging to London Destined Voyage Bristol

If Surveyed Afloat or in Dry Dock Green by Mr J. A. Green

Last Survey, No. 3 9108 Port of Lon Classed 140A-4.80

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>New Main Yard &c</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>From St</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Deerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>5 No. 12 & 14 lb</u>
Sides <u>"</u>	Ceiling <u>"</u>	Cables <u>Cast on side</u>
Planks <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Y Metal</u> When put on <u>1879</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>"</u>	Caulking of <u>Patched & resorted</u>	Cargo and Main Hatchways <u>Good</u>
General Observations, Opinion as to Class, &c. <u>"</u>	Bottom, Deck, & Waterways <u>new for</u>	Hatches <u>"</u>

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18