

# ANNUAL SURVEYS.

No.                      Survey held at London Date, first Survey 24 Feb<sup>y</sup> Last Survey 19 March 18 81  
 No. in on the L. H. Olausdale Master Bolt  
 Reg. Book. 525 Net 1102 Built at Lunderlands When built 1858  
 Tonnage { Gross 1352 By whom built Anderson  
 Under Dk. 1257 Owners Anderson  
 Port belonging to London Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Canal dry dock  
 (State Name of Dock.)

Last Survey, No. 39061 Port of London Classed 14 A1 4.80  
 Present Condition of the Decks Good Treenails Good  
 Waterways do Breasthooks and Stenson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. Y. M. When put on 80  
 Caulking of Bottom, Deck, & Waterways do  
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do Hatches do  
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 General Observations, Opinion as to Class, &c.

Metal patched where required. Main Mast and the main rigging new. This vessel appears eligible to remain as classed.  
Surveyed with ballast over the hold.

Committee's Minute Friday, April, 1st, 18 81.  
 Character assigned Cross 18A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.                      Survey held at                      Date, first Survey                      Last Survey                      18                       
 No. in on the                      Master                       
 Reg. Book.                      Net                      Built at                      When built                       
 Tonnage { Gross                      By whom built                      Owners                       
 Under Dk.                      Port belonging to                      Destined Voyage                       
 If Surveyed Afloat or in Dry Dock                       
 (State Name of Dock.)

Last Survey, No.                      Port of                      Classed                       
 Present Condition of the Decks                      Treenails                       
 Waterways                      Breasthooks and Stenson                       
 Comings                      Transoms, Pointers, and Crutches                       
 Upper Deck Beams & Fastenings                      Timbers of the Frame at the Openings                       
 Lower Deck Beams & Fastenings                      Ditto ditto at other places                       
 Planksheers                      Keelsons                       
 Sheerstrakes                      Clamps and Shelves                       
 Topsides                      Ceiling                       
 Wales                      Rudder                       
 Plank (Bottom) and Counter                      Copper or Y.M.                      When put on                       
 Caulking of Bottom, Deck, & Waterways                       
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers                      Cargo and Main Hatchways                      Hatches                       
 (If a Steam Ship, state if a Report is also sent on the Machinery)  
 General Observations, Opinion as to Class, &c.

Committee's Minute                      18                       
 Character assigned                      Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid



Holmdale



© 2021

Lloyd's Register  
Foundation