

ANNUAL SURVEYS.

40232

No. Survey held at London Date, first Survey March 16 Last Survey March 30 1881
No. in on the S Plassey Master Richards
Reg. Book. 461 Net 1683 Built at Sunderland When built 1874 Year. 5 Month.
Tonnage Gross 1764 By whom built Pile Owners G. S. Fyler & Co
Under Dk. 1584 Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Greens Dyk St & Afloat.
(State Name of Dock.)

Last Survey, No. 26244 Port of London Classed 100A 4.80
ss Ln M 179
Present Condition of the
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
(If a Steam Ship, state if a Report is also sent on the Machinery) Bottom be coated
General Observations, Opinion as to Class, &c. Bottom be coated

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, April, 1st. 1881 Senhouse Martindale,
Character assigned 100A 1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) 5/- Paid 25/4 1881

No. Survey held at London Date, first Survey March 5 Last Survey March 30 1881
No. in on the S Patriarch Master G. Pile
Reg. Book. 159 Net 1335 Built at Aberdeen When built 1869 Year. 9 Month.
Tonnage Gross 1405 By whom built Owners G. Thompson & Co
Under Dk. 1184 Port belonging to Aberdeen Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Greens Dyk Dock & Afloat
(State Name of Dock.)

Last Survey, No. 27242 Port of London Classed 100A 1.6.80
ss Ln M 277
Present Condition of the
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
(If a Steam Ship, state if a Report is also sent on the Machinery) Bottom be coated
General Observations, Opinion as to Class, &c. Bottom be coated

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, April, 1st. 1881 Senhouse Martindale,
Character assigned 100A 1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) 5/- Paid 25/4 1881

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

ANNUAL SURVEYS

Plaza
Bar

No.

Date, first survey

When built

Owner

Designated purpose

If surveyed abroad or in dry dock

Last survey, No.

Present condition of the

hull

Waterways

Engine

Upper Deck Beam & Lashing

Lower Deck Beam & Lashing

Plank

Stowage

Trunks

Walls

Plank (Bottom) and Counter

Engine Room

General Observations, opinion as to class, etc.

Committee's Minutes

Character assigned

18

Date, first survey

When built

Owner

Designated purpose

If surveyed abroad or in dry dock

Last survey, No.

Present condition of the

hull

Waterways

Engine

Upper Deck Beam & Lashing

Lower Deck Beam & Lashing

Plank

Stowage

Trunks

Walls

Plank (Bottom) and Counter

Engine Room

General Observations, opinion as to class, etc.

18



© 2021

Lloyd's Register
Foundation