

ANNUAL SURVEYS.

40258

No. Survey held at London Date, first Survey March 7th Last Survey March 12th 1881
 No. in on the SS Eldorado Master J. C. Kerr
 Reg. Book. 266 Net 2157 Built at Hull When built 1873 Month. 3
 Tonnage Gross 3332 By whom built Earls & Co Owners A. Gray & S. Surves
 Under Dk. 2128 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St. & after
 (State Name of Dock.)

Last Survey, No. 27379 Port of London

Classed 100 A 1 7.80
 Years assigned. SS in M 77
 Character in Register Book.

Present Condition of the
 Decks Good Treennails Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of "
 Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 (If a Steam Ship, state if a Report is also sent on the Machinery yes)
 General Observations, Opinion as to Class, &c. Bottom & coated

*She is now in an efficient state
 and eligible to remain as classed.*

Committee's Minute Friday, April. 8th. 1881.

Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. Net Built at When built
 Tonnage Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of

Classed
 Years assigned.
 Character in Register Book.

Present Condition of the
 Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of
 Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned



© 2021

Lloyd's Register
Foundation