

# ANNUAL SURVEYS.

40261

(Received at London Office, 14 7. 4. 81)

No.          Survey held at London Date, first Survey 24 March Last Survey 24 March 18 81  
 on the Harwar Master Hutchins  
 No. in Reg. Book. 253 Net 1300 Built at Belfast When built 1864 9  
 Tonnage Gross 1456 Under Dk. 1214 By whom built Harland Owners J. Willis & Son  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Canal dry dock (State Name of Dock.)

Last Survey, No. 46522 Port of Iron Classed SA 1 5.80  
 Character in Register Book. S.P.H. 78

Present Condition of the Decks	<u>Good</u>	Treenails <u>Quits</u>	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>
Wales	<u>do</u>	Rudder	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M. <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	<u>do</u>
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	Scuppers	<u>do</u>
General Observations, Opinion as to Class, &c.	<u>Bottom cleaned and recoated. This vessel appears eligible to remain as classed.</u>		

Committee's Minute Friday, April 8th, 18 81  
 Character assigned SA Surveyor to Lloyd's Register of British and Foreign Shipping. J.W. Certificate (if required, to be sent as per margin) Paid 18

No.          Survey held at London Date, first Survey 28 March Last Survey 24 March 18 81  
 on the Goldingham Master Phillips  
 No. in Reg. Book. 1024 Net 1059 Built at Lpool When built 1866 1  
 Tonnage Gross 1072 Under Dk. 991 By whom built Hart Owners J. Willis & Son  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Canal dry dock (State Name of Dock.)

Last Survey, No. 46307 Port of Iron Classed SA 1 4.80  
 Character in Register Book. S.P.H. 78

Present Condition of the Decks	<u>Good</u>	Treenails <u>Quits</u>	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>
Wales	<u>do</u>	Rudder	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M. <input checked="" type="checkbox"/> When put on <input checked="" type="checkbox"/>	<u>do</u>
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	Scuppers	<u>do</u>
General Observations, Opinion as to Class, &c.	<u>Bottom cleaned and recoated. This vessel appears in good condition and eligible to remain as classed. Surveyed with part of the outward cargo in lower hold from the fore mast to mainmast.</u>		

Committee's Minute Friday, April 8th, 18 81  
 Character assigned SA Surveyor to Lloyd's Register of British and Foreign Shipping. J.W. Certificate (if required, to be sent as per margin) Paid 18

Committee's Minute Friday, April 8th, 18 81  
 Character assigned SA Surveyor to Lloyd's Register of British and Foreign Shipping. J.W. Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

Dharmar  
&  
Coldenham



© 2021

Lloyd's Register  
Foundation