

ANNUAL SURVEYS.

40,279

No. _____ Survey held at London Date, first Survey 28th March Last Survey 30th March 1881
 No. in on the Iron Scw. Sr. "Mid Surrey" Master G. Dobbyn.
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage ^{Net} 566 Built at Newcastle When built 1870
^{Gross} 903 ^{Under Dk.} 805 By whom built Palmer Owners Harris & Dixon.
 Port belonging to London Destined Voyage Tyne
 If Surveyed Afloat or in Dry Dock In Limekiln Dry Dock.
(State Name of Dock.)

Last Survey, No. 26599 Port of Iron Classed 90 A. 1.
 Years assigned. 4.80 Character in Register Book.
L.S. Lon. N^o 3-79.

Present Condition of the Decks <u>good</u>	Treenails <u>rivets</u> — <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>J^o</u>	Breasthooks and Stemson <u>J^o</u>	Pumps <u>J^o</u>
Comings <u>J^o</u>	Transoms, Pointers , and Crutches <u>J^o</u>	Boats <u>J^o</u>
Upper Deck Beams & Fastenings <u>J^o</u>	Timbers of the Frame at the Openings <u>J^o</u>	Masts, Yards, &c. <u>J^o</u>
Lower Deck Beams & Fastenings <u>J^o</u>	Ditto ditto at other places <u>J^o</u>	Condition, how ascertained <u>from the deck</u>
Planksheers <u>J^o</u>	Keelsons <u>J^o</u>	Sails <u>good</u>
Sheerstrakes <u>J^o</u>	Clamps and Shelves <u>J^o</u>	Anchors, No. of <u>3 B. 1 S. 2 K</u>
Topsides <u>J^o</u>	Ceiling <u>J^o</u>	Cables <u>complete</u>
Wales <u>J^o</u>	Rudder <u>J^o</u>	Hawsers and Warps <u>sufficient</u>
Plank (Bottom) and Counter <u>J^o</u>	Copper or Y.M. <u>When put on</u>	Standing and Running Rigging <u>good</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	
Coal Bunkers, Openings, Lids, &c. <u>good</u>		
Scuppers <u>good</u>		
Cargo and Main Hatchways <u>good</u>		
Hatches <u>good</u>		

General Observations, Opinion as to Class, &c.
The bottom has been examined, cleaned & coated. Three pintles of the rudder renewed. This vessel appears to be in good and efficient condition, and eligible to remain as classed

Committee's Minute Thursday, April, 11th 1881. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 90 A 1 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage ^{Net} _____ Built at _____ When built _____
^{Gross} _____ ^{Under Dk.} _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. _____ Character in Register Book.

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	
Coal Bunkers, Openings, Lids, &c. _____		
Scuppers _____		
Cargo and Main Hatchways _____		
Hatches _____		

General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

