

ANNUAL SURVEYS.

No. 40286 Survey held at London Date, first Survey 24 March Last Survey 7 April 18 81
 No. in on the "Langstone" Master J. Ferguson
 Reg. Book. 196 Net 748 Built at Sunderland When built 1869
 Tonnage Gross 748 Under Dk. 699 By whom built Pile Owners Thos. Saville & Co.
 Port belonging to Southampton Destined Voyage N. Zealand
 If Surveyed Afloat or in Dry Dock Ruffs dry dock (State Name of Dock.)

Last Survey, No. 46673 Port of Iron Classed 5.80
 Present Condition of the Decks Good Reinails Puncts Roof
 Waterways de Breasthooks and Stenson de
 Comings de Transoms, Pointers, and Crutches de
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
 Lower Deck Beams & Fastenings de Ditto ditto at other places de
 Planksheers de Keelsons de
 Sheerstrakes de Clamps and Shelves de
 Topsides de Ceiling de
 Wales de Rudder de
 Plank (Bottom) and Counter de Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights de Coal Bunkers, Openings, Lids, &c. de Scuppers de Cargo and Main Hatchways de Hatches de
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated - the rudder pintle renewed. This vessel appears eligible to remain as classed

Committee's Minute Tuesday, April 19th 1881. W. B. Longdon
 Character assigned W. B. Longdon Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 18

No. 40287 Survey held at London Date, first Survey 5 April Last Survey 8 April 18 81
 No. in on the "Oaklands" Master L. Crook
 Reg. Book. 8 Net 955 Built at Dunder When built 1876
 Tonnage Gross 1613 Under Dk. 894 By whom built Gowlay Owners Lawrence
 Port belonging to London Destined Voyage Port Augusta
 If Surveyed Afloat or in Dry Dock West. I. dry dock (State Name of Dock.)

Last Survey, No. 46692 Port of Iron Classed 100.4/5.80
 Present Condition of the Decks Good Reinails Puncts Roof
 Waterways de Breasthooks and Stenson de
 Comings de Transoms, Pointers, and Crutches de
 Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
 Lower Deck Beams & Fastenings de Ditto ditto at other places de
 Planksheers de Keelsons de
 Sheerstrakes de Clamps and Shelves de
 Topsides de Ceiling de
 Wales de Rudder de
 Plank (Bottom) and Counter de Copper or Y.M. ✓ When put on ✓
 Engine Room Skylights de Coal Bunkers, Openings, Lids, &c. de Scuppers de Cargo and Main Hatchways de Hatches de
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated - Rudder pintles renewed - This vessel appears eligible to remain as classed

Committee's Minute Tuesday, April 19th 1881. W. B. Longdon
 Character assigned W. B. Longdon Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 18

Langston

Barclay



© 2021

Lloyd's Register
Foundation