

ANNUAL SURVEYS.

40290

No. Survey held at London Date, first Survey 2 April Last Survey 2 April 1881
No. in on the Barque "Agatha" Master Storv
Reg. Book. 241 Net 431 Built at Sunderland When built 1866 Year. 1 Month.
Tonnage Gross 431 Under Dk. 407 By whom built Hills Owners Hankey & Co
Port belonging to London Destined Voyage West Indies
If Surveyed Afloat or in Dry Dock West. I. dry dock (State Name of Dock.)

Last Survey, No. 3863 Port of Lon Classed 16 A1 11.79
H.T. 71.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>
Wales	<u>do</u>	Rudder	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M. <u>Y.M.</u> When put on <u>1879</u>	
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.		Windlass and Capstan	<u>Good</u>
Scuppers	<u>do</u>	Pumps	<u>Two</u>
Cargo and Main Hatchways	<u>do</u>	Boats	<u>Three</u>
Hatches	<u>do</u>	Masts, Yards, &c.	<u>do</u>
		Condition, how ascertained	<u>from deck</u>
		Sails	<u>well found</u>
		Anchor, No. of	<u>20. 1 S & Hedges</u>
		Cables	<u>complete</u>
		Hawsers and Warps	<u>sufficient</u>
		Standing and Running Rigging	<u>good</u>

General Observations, Opinion as to Class, &c. Yellow Metal repaired. This vessel appears
eligible to remain as classed.
Surveyed with ballast and damage in main hold

Committee's Minute Tuesday, April, 19th 1881. W. B. Longdon
Character assigned 10 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Net Built at When built Year. Month.
Tonnage Gross Under Dk. By whom built Owners
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the Decks		Treenails	
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings		Ditto ditto at other places	
Planksheers		Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	
Plank (Bottom) and Counter		Copper or Y.M. <u> </u> When put on <u> </u>	
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.		Windlass and Capstan	
Scuppers		Pumps	
Cargo and Main Hatchways		Boats	
Hatches		Masts, Yards, &c.	
		Condition, how ascertained	
		Sails	
		Anchor, No. of	
		Cables	
		Hawsers and Warps	
		Standing and Running Rigging	

General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

Agatha



© 2021

Lloyd's Register
Foundation