

4/81

# ANNUAL SURVEYS.

140202

No.            Survey held at London Date, first Survey April 9 Last Survey April 11 1881  
(Received at London Office, 21. 4. 81)  
No. in on the SS Manora Master Cosens  
Reg. Book. 211 Net 2120 Built at Grimbarton When built 1878 Year. 3 Month.             
Tonnage Gross 8242 By whom built Denny Owners S Macneil & Co Denny  
Under Dk. 3166 Port belonging to Glasgow Destined Voyage             
If Surveyed Afloat or in Dry Dock Pontoon Victoria St  
(State Name of Dock.)

Last Survey, No. 27832 Port of Glasgow Classed 100A. S. 80  
Present Condition of the  
Decks good Treenails Rivets good  
Waterways u Breasthooks and Stemson u  
Comings u Transoms, Pointers, and Crutches u  
Upper Deck Beams & Fastenings u Timbers of the Frame at the Openings u  
Lower Deck Beams & Fastenings u Ditto ditto at other places u  
Planksheers u Keelsons u  
Sheerstrakes u Clamps and Shelves u  
Topsides u Ceiling u  
Wales u Rudder u  
Plank (Bottom) and Counter u Copper or Y.M. Coated When put on Mon  
Caulking of Bottom, Deck, & Waterways good  
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches u  
(If a Steam Ship, state if a Report is also sent on the Machinery           )  
General Observations, Opinion as to Class, &c. Bottom to be coated


*She is now in an efficient state and eligible to remain as classed.*

Committee's Minute Friday, April 22nd 1881. Senhouse Martindale  
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin)            Paid 18

No.            Survey held at            Date, first Survey            Last Survey            18            
No. in on the            Master             
Reg. Book.            Net            Built at            When built            Year.            Month.             
Tonnage Gross            By whom built            Owners             
Under Dk.            Port belonging to            Destined Voyage             
If Surveyed Afloat or in Dry Dock             
(State Name of Dock.)

Last Survey, No.            Port of            Classed             
Present Condition of the  
Decks            Treenails             
Waterways            Breasthooks and Stemson             
Comings            Transoms, Pointers, and Crutches             
Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
Lower Deck Beams & Fastenings            Ditto ditto at other places             
Planksheers            Keelsons             
Sheerstrakes            Clamps and Shelves             
Topsides            Ceiling             
Wales            Rudder             
Plank (Bottom) and Counter            Copper or Y.M.            When put on             
Caulking of Bottom, Deck, & Waterways             
Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
(If a Steam Ship, state if a Report is also sent on the Machinery           )  
General Observations, Opinion as to Class, &c.           

Committee's Minute            18            
Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin)            Paid 18



© 2021

Lloyd's Register Foundation

LON 665-0427