

# ANNUAL SURVEYS.

40327

No. \_\_\_\_\_ Survey held at London Date, first Survey 11 April Last Survey 12 April 1881  
 No. in on the S.S. Coniston Master D. Insdale  
 Reg. Book. \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage { Net 1491 Built at Newcastle When built 1880 10  
 { Gross 2258  
 { Under Dk. 2154 By whom built Leslie Owners Milburn  
 Port belonging to London Destined Voyage Pont de Salle  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ (State Name of Dock.) Poplar-dry dock

Last Survey, No. 15204 Port of hwc Classified \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. 100A  
11-80

Present Condition of the Decks	<u>Good</u>	<u>Good</u>	
Waterways	<u>do</u>	Breasthooks and Stenson	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the Openings	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto ditto at other places	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>
Wales	<u>do</u>	Rudder	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>	Copper or Y.M. When put on	_____
Engine Room Skylights	<u>do</u>	Caulking of Bottom, Deck, & Waterways	<u>do</u>
Coal Bunkers, Openings, Lids, &c.	<u>do</u>	Scuppers	<u>do</u>
Cargo and Main Hatchways	<u>do</u>	Hatches	<u>do</u>

General Observations, Opinion as to Class, &c. Bottom cleaned and recoated. This vessel appears eligible to remain as classed.

Committee's Minute \_\_\_\_\_ Friday, April, 29th 1881.  
 Character assigned 100A J.W. Congdon Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 { Gross \_\_\_\_\_  
 { Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ (State Name of Dock.) \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classified \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book. \_\_\_\_\_

Present Condition of the Decks			
Waterways		Breasthooks and Stenson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings		Ditto ditto at other places	
Planksheers		Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	
Plank (Bottom) and Counter		Copper or Y.M. When put on	_____
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.		Scuppers	
Cargo and Main Hatchways		Hatches	

General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.



Coniston



© 2021

Lloyd's Register  
Foundation