

# ANNUAL SURVEYS.

No.          Survey held at London Date, first Survey March 15 Last Survey April 18 81  
 No. in on the SS Tevist Master W Nesbit  
 Reg. Book. 65 Tonnage 1345 Built at Sunderland When built 1871 . 6  
 By whom built Saing Owners C. M. Norwood & Co  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Penryn Victoria St

40329  
6.4.81

Last Survey, No. 12558 Port of Sld Classed 100A 12.80  
 Present Condition of the Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coutin When put on now  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom & coutin.

*She is now in an efficient state and eligible to remain as clasped.*

Committee's Minute Friday, April, 29th 1881. Senhouse Martindale  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)          Paid          18         

No.          Survey held at          Date, first Survey          Last Survey 18  
 No. in on the          Master           
 Reg. Book.          Tonnage          Built at          When built           
 By whom built          Owners           
 Port belonging to          Destined Voyage           
 If Surveyed Afloat or in Dry Dock         

Last Survey, No.          Port of          Classed           
 Present Condition of the Decks          Treenails           
 Waterways          Breasthooks and Stemson           
 Comings          Transoms, Pointers, and Crutches           
 Upper Deck Beams & Fastenings          Timbers of the Frame at the Openings           
 Lower Deck Beams & Fastenings          Ditto ditto at other places           
 Planksheers          Keelsons           
 Sheerstrakes          Clamps and Shelves           
 Topsides          Ceiling           
 Wales          Rudder           
 Plank (Bottom) and Counter          Copper or Y.M.          When put on           
 Caulking of Bottom, Deck, & Waterways           
 Engine Room Skylights          Coal Bunkers, Openings, Lids, &c.          Scuppers          Cargo and Main Hatchways          Hatches           
 General Observations, Opinion as to Class, &c.         

Committee's Minute 18  
 Character assigned          Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required)          Paid          18



