

ANNUAL SURVEYS.

40340

No. Survey held at London Date, first Survey April Last Survey 19 April 18 81
 No. in on the "Pouterbeck" Master Stitt
 Reg. Book. 631 Net 930 Built at Whitehaven When built 1875 Month. 4
 Tonnage Gross 943 Under Dk. 896 By whom built Whitehaven S. Co Owners Davidsons
 Port belonging to Whitehaven Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock West-Ind. dry dock
 (State Name of Dock.)

Last Survey, No. 26473 Port of Iron

Present Condition of the Decks Good Treasonably Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on
 Caulking of Bottom, Deck, & Waterways do
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do Hatches do
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Classed 100 A1
 Years assigned. 4 80
 Character in Register Book. P.S. Nov. 80

Bottom recoated and pintles of rudder bushed. This vessel appears eligible to remain as classed.
Surveyed with ballast in main hold.

Committee's Minute

Friday, May, 6th 18 81.

Character assigned

100 A1

Thos. Longdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at London Date, first Survey 20 April Last Survey 21 April 18 81
 No. in on the "Rakaria" Master L. Bone
 Reg. Book. 49 Net 1022 Built at Sld When built 1877 Month. 11
 Tonnage Gross 1057 Under Dk. 893 By whom built Blumer Owners New L. S. Co
 Port belonging to Littleton Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Canal dry dock
 (State Name of Dock.)

Last Survey, No. 23435 Port of Iron

Present Condition of the Decks Good Treasonably Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. ✓ When put on ✓
 Caulking of Bottom, Deck, & Waterways do
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do Hatches do
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Classed 100 A1 5-79
 Years assigned. 2 81-78
 Character in Register Book.

Bottom cleaned and recoated. This vessel appears eligible to remain as classed.

Committee's Minute

Friday, May, 6th 18 81.

Character assigned

100 A1

Thos. Longdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

© 2021

LOW 665-0467

Contenker

Rachan



© 2021

Lloyd's Register
Foundation