

Change flowers 40345
REPORT of SURVEY for REPAIRS, &c.

No. 839 on the Duke of Cornwall, late City of Madras Master J. Houston
No. in Survey held at London Date, first Survey 18 March Last Survey 22 April 188 1
Reg. Book. C 839 on the Duke of Cornwall, late City of Madras Master J. Houston
Official Number 953.52 Tonnage under Tonnage Deck 953.52
Ditto of Spar Deck, or Avoning Deck 45.83 Built at Glasgow When built 1859
Ditto of Poop 6.51 Owners Montgomery & Workman Port belonging to Glasgow
Ditto of Raised Qr. Dk. 28.40 Residence Office 17 Gracechurch Street
Ditto of Houses on Deck 103.4.26 By whom built Ruggs Dry Dock
Gross Tonnage 34.91 Destined Voyage Alger Bay
Crew Space, as per Rule 99.35 If Surveyed Afloat or in Dry Dock Ruggs Dry Dock
Register Tonnage, cut on Beam 99.35 (State Name of Dock)
Engine Room Reg. Tons as St' mer, cut on Bm.
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
Last Survey, No. 2722 Port Quor Character in Register Book 1 680
REPAIRS, OR EXAMINATION AS PER RULE
Cause of Repairs to be clearly stated.

This vessel had 4 bulkheads. The second bulkhead from forward has now been removed, leaving about 8' round the sides inside the frames; the third bulkhead has been removed in a similar way up to the Hold beam only, the upper part of bulkhead remaining.
Rudder pintles knuckled and bottom recoated.

Present Condition of the								
Decks	Good	Greenails	Rivets	Good	Windlass and Capstan	Good		
Waterways	do	Breasthooks and Stemson		do	Pumps	two	do	
Comings	do	Transoms, Pointers, and Crutches		do	Boats	four	do	
Upper Deck Beams & Fastenings	do	Timbers of the Frame at the openings		do	Masts, Yards, &c.		do	
Lower Deck Beams & Fastenings	do	Ditto Ditto at other places		do	Condition, how ascertained	from deck		
Planksheers	do	Keelsons		do	Sails	well found		
Sheerstrakes	do	Clamps and Shelves		do	Anchors	No. of 30, 15, 10, 5		
Topsides	do	Ceiling		do	Cables	complete		
Wales	do	Rudder		do	Hawsers and Warps	sufficient		
Plank (Bottom) and Counter	do	Copper (or Y.M.)	✓ When put on ✓		Standing & Running Rigging	good		
Engine Room Skylights		Caulking of			Cargo and Main Hatchways	do	Hatches	do
		Bottom, Deck, & Waterways		do				
		Coal Bunker, Openings, Lids, &c.		Scuppers	do			

General Observations, Opinion as to Class, &c.
This vessel appears in good condition and eligible to remain as classed

The Amount of Entry Fee ... £ 1 : : : received by me, 4th May 1881
Special ... £ 2 : 2 :
Certificate (if required) to be sent as per margin... £ - : 5 :
(Travelling Expenses, if any, £)
Committee's Minute Friday, May, 1881
Character assigned FR
Surveyor to Lloyd's Register of British and Foreign Shipping.
© 2021 Lloyd's Register Foundation
LON 666-0473

122
Book of Common Prayer



© 2021

Lloyd's Register
Foundation

REPORT OF SURVEY FOR