

ANNUAL SURVEYS.

40740

No. Survey held at London Date, first Survey 2 May Last Survey 12 May 18 81
(Received at London Office, ... (Rec'd 17.5.81.)
 No. in on the S. Wairoa Master Adams
 Reg. Book. 31 Year. Month.
 Tonnage Net 1015 Built at Newcastle When built 1875 11
Gross 1057 Under Dk. 885 By whom built Palmer & Co Owners New L. S. Comp^y
 Port belonging to Littleton Destined Voyage Wellington
 If Surveyed Afloat or in Dry Dock Canal dry dock
(State Name of Dock.)

Last Survey, No. 27557 Port of Iron Classed 100 A 1 7-8
Years assigned. Character in Register Book
 Present Condition of the Decks Good Iron Roof
 Waterways do Breasthooks and Stenson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways do
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do Hatches do
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated - This vessel appears in good condition and eligible to remain as classed

Committee's Minute Friday, May, 20th 18 81. J. B. Bond
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at London Date, first Survey 6 May Last Survey 9 May 18 81
 No. in on the S. Loch Long Master Boldchild
 Reg. Book. 614 Year. Month.
 Tonnage Net 1203 Built at Glasgow When built 1876 11
Gross 1261 Under Dk. 1104 By whom built Stimpson Owners General S. Co
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Retained dry dock
(State Name of Dock.)

Last Survey, No. 19376 Port of Iron Classed 100 A 1
Years assigned. Character in Register Book
 Present Condition of the Decks Good Iron Roof
 Waterways do Breasthooks and Stenson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways do
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do Hatches do
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Bottom cleaned and recoated - This vessel appears eligible to remain as classed - Rudder pintle bushed

Surveyed with ballast in main hold and cement (cargo) in after hold

Committee's Minute Friday, May, 20th 18 81. J. B. Bond
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

*24 Clas: 30/5/81
 Rem 13/6/81*

Warren
&
Luch King



© 2021

Lloyd's Register
Foundation

ANNUAL SUBS