

# REPORT of SURVEY for REPAIRS, &c.

No. 456 on the "Drumlaire" 1361  
No. in Survey held at London Date, first Survey 4 May Last Survey 16 May 1881  
Reg. Book. 456 Master W. Edmondson  
TONNAGE under Tonnage Deck 1361 Built at Port Glasgow When built 1876  
Ditto of Spar Deck, or Avoing Deck  
Ditto of Poop  
Ditto of Raised Or. Dk.  
Ditto of Houses on Deck  
Ditto of Forecastle  
Gross Tonnage 1482 Owners Gillison & Chadwick Port belonging to Spool  
Crew Space, as per Rule  
Register Tonnage, out on Beam 1425 By whom built Russell Destined Voyage Left home to Galbraith  
Engine Room  
Reg. Tons as St'mer, out on Bm.  
If Surveyed Afloat or in Dry Dock Raplar dry dock  
(State Name of Dock)  
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 100 A1.  
Character in Register Book. 12.80  
Last Survey, No. 27304 Port Iron  
REPAIRS, OR EXAMINATION AS PER RULE P. S. R. 1  
Cause of Repairs to be clearly stated.

The special surveying has been carried out in part only viz! - A strake of Ceiling in flat removed from the fourth station before the after Hatch forward to the fore mast, and the liner strake from the first named point to the pump well on the port side - and on the starboard side from the first named point forward to the fourth station before main Hatchway. Cement examined and found in good condition and adhering well to the plating &c. Bottom cleaned and recoated.

Repairs after damage! - one plate of sheerstrake and two other plates in topside strakes renewed on port side aft and some small repairs to stringer plate.

Present Condition of the	Good	Greenails	Good	Windlass and Capstan	Good
Decks		Reinforced			
Waterways	de	Breasthooks and Stemson	de	Pumps	two de
Trunks	de	Transoms, Pointers, and Crutches	de	Boats	four de
Upper Deck Beams & Fastenings	de	Timbers of the Frame at the openings	de	Masts, Yards, &c.	de
Lower Deck Beams & Fastenings	de	Ditto Ditto at other places	de	Condition, how ascertained	from deck
Keelsons	de	Keelsons	de	Sails	well found
Clamps and Shelves	de	Clamps and Shelves	de	Anchors	No. of 30. 15 & 10 lbs
Ceiling	de	Ceiling	de	Cables	complete
Rudder	de	Rudder	de	Hawsers and Warps	sufficient
Copper (or Y.M.)	de	Copper (or Y.M.)	de	Standing & Running Rigging	good
When put on		When put on		Cargo and Main Hatchways	de
Caulking of		Caulking of		Hatches	de
Bottom, Deck, & Waterways	de	Bottom, Deck, & Waterways	de		
Engine Room Skylights		Coal Bunker, Openings, Lids, &c.			
Scuppers		Scuppers			

General Observations, Opinion as to Class, &c.

This vessel appears in good condition and it is submitted she may remain as classed on the understanding that the special survey be completed at Galbraith, to which the owners appear from their letter to be agreeable

The Amount of Entry Fee ... £ 2 : 2 : 31/5 received by me, W. Edmondson

Certificate (if required to be sent as per minute) ... £ 5 : -

(Travelling Expenses, if any, ...)

Committee's Minute

Friday, May, 27th 1881.

Character assigned

100 A1

W. Edmondson  
28/5/81

W. Edmondson  
31/5/81

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register Foundation

L07665-0526