

ANNUAL SURVEYS.

407443

21.5-81

No. in Reg. Book. on the 45 Supp 1589 2034 Tonnage 1589 2034 Built at Glasgow When built 1880 11

Survey held at London Date, first Survey May 10th Last Survey May 17th 18 81

Master S. J. Bergemann Owners A. Gray & S. James

By whom built J. Inglis Destined Voyage Calcutta

Port belonging to Glasgow

If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 5282 Port of GL

Classed 100 A 12.80

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	<u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Canted</u> When put on <u>now</u>	<u>"</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>"</u>	<u>"</u>
Coal Bunker, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
General Observations, Opinion as to Class, &c. <u>Bottom ke canted</u>		

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, May, 27th 18 81.

Character assigned 100 A 12.80

Senhouse Martindale Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18 81

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master

Tonnage Built at When built

By whom built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

Present Condition of the Decks <u> </u>	Treenails <u> </u>	<u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	<u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	<u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	<u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	<u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	<u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	<u> </u>
Topsides <u> </u>	Ceiling <u> </u>	<u> </u>
Wales <u> </u>	Rudder <u> </u>	<u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	<u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	<u> </u>
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	Cargo and Main Hatchways <u> </u>
General Observations, Opinion as to Class, &c. <u> </u>		

Committee's Minute 18

Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) Paid 18

Cambridge
17 Oct Sunday see
in office book

