

ANNUAL SURVEYS.

40473

No. 1309 Survey held at London Date, first Survey 1st March Last Survey 1st June 1881
No. in on the Iron Pad. Ste. "Swift" Master W. Butcher
Reg. Book. 1309 Net 363 Built at Stockton Year. 1875 Month. 6th
Tonnage Gross 627 Under Dk. 556 By whom built Pearse Owners General Steam Navigation Co.
Port belonging to London Destined Voyage To the Continent
If Surveyed Afloat or in Dry Dock On the Gridiron of the General Steam Navigation Co.
(State Name of Dock.)

Last Survey, No. 26075 Port of Iron

Present Condition of the

Decks good
Waterways D^o
Comings D^o
Upper Deck Beams & Fastenings D^o
Lower Deck Beams & Fastenings D^o
Planksheers D^o
Sheerstrakes D^o
Topsides D^o
Wales D^o
Plank (Bottom) and Counter D^o

Treenails rivets good
Breasthooks and Stemson D^o
Transoms, Pointers, and Crutches D^o
Timbers of the Frame at the Openings D^o
Ditto ditto at other places D^o
Keelsons D^o
Clamps and Shelves D^o
Ceiling D^o
Rudder D^o
Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways good

Classed S.S. Lon. N^o 1-80. Character in Register Book. 100 A. 1.
2.80

Windlass and Capstan good
Pumps D^o
Boats D^o
Masts, Yards, &c. D^o
Condition, how ascertained from the deck
Sails good
Anchors, No. of 3 B. 15. & kedges.
Cables complete
Hawsers and Warps sufficient
Standing and Running Rigging good

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.

The bottom has been examined, cleaned & coated. The upper deck recaulked.
In this case an untested bower anchor, of full weight, has been put on board to supply the place of one deficient. The Owners have promised to replace the untested anchor with one tested as required by Rule, and in view of this the Owners, who have a number of anchors in stock are making arrangements for sending them to the Tyne for testing so as to be available when required and at the same time fulfil the Rule in supplying them to the Company's Classed vessels when required. It is submitted that she may remain as classed on the understanding stated above.

Committee's Minute Friday, June, 3rd 18 81

Character assigned 100 A. 1.

J. A. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
Reg. Book. Net Built at Year. Month.
Tonnage Gross Under Dk. By whom built When built Owners

Port belonging to Destined Voyage

If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of

Classed Character in Register Book.

Present Condition of the

Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelves
Ceiling
Rudder
Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LD 4665-0630