

ANNUAL SURVEYS.

40495
8.6.81

No. _____ Survey held at London Date, first Survey May 25 Last Survey June 2^d 1881
 No. in on the SS Tanfield Master G Bowdler
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage ^{Net} 482 Built at Newcastle When built 1864 12
_{Gross} 765 _{Under Dk.} 712 By whom built Palmer Owners J Fenwick & Son
 Port belonging to London Destined Voyage Tyne
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St
(State Name of Dock.)

Last Survey, No. 46538 Port of Iron Classed C 1.5.80
 Present Condition of the Decks good Treenails Rivets good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. New Main & Mizzen Masts
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained Examined
 Topsides " Ceiling " Sails "
 Wales " Rudder " Anchors, No. of 1 No. St & 1 Redys
 Plank (Bottom) and Counter " ~~Copper or Y.M. Coated~~ When put on new Cables Part on St good
 Caulking of Bottom, Deck, & Waterways good Standing and Running Rigging "
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches "
 General Observations, Opinion as to Class, &c. Some repairs, a short plate renewed & another patched. Bottom &c coated.


She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, June, 10th 1881. Senhouse Martindale
 Character assigned A 1 B W Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage ^{Net} _____ Built at _____ When built _____
_{Gross} _____ _{Under Dk.} _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____ Windlass and Capstan _____
 Comings _____ Transoms, Pointers, and Crutches _____ Pumps _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Boats _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Masts, Yards, &c. _____
 Planksheers _____ Keelsons _____ Condition, how ascertained _____
 Sheerstrakes _____ Clamps and Shelves _____ Sails _____
 Topsides _____ Ceiling _____ Anchors, No. of _____
 Wales _____ Rudder _____ Cables _____
 Plank (Bottom) and Counter _____ ~~Copper or Y.M.~~ When put on _____ Hawfers and Warps _____
 Caulking of Bottom, Deck, & Waterways _____ Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____



The Surveys are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

LON665-0656

No.	Date	Part	Class
1	1871	1	1
2	1872	1	1
3	1873	1	1
4	1874	1	1
5	1875	1	1
6	1876	1	1
7	1877	1	1
8	1878	1	1
9	1879	1	1
10	1880	1	1
11	1881	1	1
12	1882	1	1
13	1883	1	1
14	1884	1	1
15	1885	1	1
16	1886	1	1
17	1887	1	1
18	1888	1	1
19	1889	1	1
20	1890	1	1
21	1891	1	1
22	1892	1	1
23	1893	1	1
24	1894	1	1
25	1895	1	1
26	1896	1	1
27	1897	1	1
28	1898	1	1
29	1899	1	1
30	1900	1	1