

# ANNUAL SURVEYS.

40503  
868

**No.** \_\_\_\_\_ **Survey held at** London **Date, first Survey** May 27 **Last Survey** June 3<sup>rd</sup> 1881  
(Received at London Office,)  
**No. in on the** SS Lounda **Master** Jempton  
**Reg. Book.** 395  
**Tonnage** Net 1943 **Built at** Sumbarton **When built** 1875 Year. 10 Month.  
Gross 2977 **By whom built** Senny **Owners** J Macneil & P Senny  
Under Dk. 2920 **Port belonging to** Glasgow **Destined Voyage** Australia  
**If Surveyed Afloat or in Dry Dock** \_\_\_\_\_  
(State Name of Dock.)

**Last Survey, No.** 28743 **Port of** Iron **Classed** 100A 10.80  
Years assigned. Character in Register Book.  
**Present Condition of the**  
**Decks** Good **Treenails** Pivots Good  
**Waterways** \_\_\_\_\_ **Breasthooks and Stenson** \_\_\_\_\_  
**Comings** \_\_\_\_\_ **Transoms, Pointers, and Crutches** \_\_\_\_\_  
**Upper Deck Beams & Fastenings** \_\_\_\_\_ **Timbers of the Frame at the Openings** \_\_\_\_\_  
**Lower Deck Beams & Fastenings** \_\_\_\_\_ **Ditto ditto at other places** \_\_\_\_\_  
**Planksheers** \_\_\_\_\_ **Keelsons** \_\_\_\_\_  
**Sheerstrakes** \_\_\_\_\_ **Clamps and Shelves** \_\_\_\_\_  
**Topsides** \_\_\_\_\_ **Ceiling** \_\_\_\_\_  
**Wales** \_\_\_\_\_ **Rudder** \_\_\_\_\_  
**Plank (Bottom) and Counter** \_\_\_\_\_ **Copper or Y.M.** Coated **When put on** Now  
**Engine Room Skylights** Good **Coal Bunkers, Openings, Lids, &c.** Good **Scuppers** Good **Cargo and Main Hatchways** Good **Hatches** \_\_\_\_\_  
**General Observations, Opinion as to Class, &c.** Bottom to be coated

*She is now in an efficient state  
and eligible to remain as classed*

**Committee's Minute** Friday, June, 10th 1881. Senhouse Martindale  
**Character assigned** 100A JRM **Surveyor to Lloyd's Register of British and Foreign Shipping.**  
**Certificate** (if required, to be sent as per margin) \_\_\_\_\_ **Paid** \_\_\_\_\_ **18** \_\_\_\_\_

**No.** \_\_\_\_\_ **Survey held at** \_\_\_\_\_ **Date, first Survey** \_\_\_\_\_ **Last Survey** \_\_\_\_\_ 18\_\_\_\_  
**No. in on the** \_\_\_\_\_ **Master** \_\_\_\_\_  
**Reg. Book.** \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_  
**Tonnage** Net \_\_\_\_\_ **Built at** \_\_\_\_\_ **When built** \_\_\_\_\_  
Gross \_\_\_\_\_ **By whom built** \_\_\_\_\_ **Owners** \_\_\_\_\_  
Under Dk. \_\_\_\_\_ **Port belonging to** \_\_\_\_\_ **Destined Voyage** \_\_\_\_\_  
**If Surveyed Afloat or in Dry Dock** \_\_\_\_\_  
(State Name of Dock.)

**Last Survey, No.** \_\_\_\_\_ **Port of** \_\_\_\_\_ **Classed** \_\_\_\_\_  
Years assigned. Character in Register Book.  
**Present Condition of the**  
**Decks** \_\_\_\_\_ **Treenails** \_\_\_\_\_  
**Waterways** \_\_\_\_\_ **Breasthooks and Stenson** \_\_\_\_\_  
**Comings** \_\_\_\_\_ **Transoms, Pointers, and Crutches** \_\_\_\_\_  
**Upper Deck Beams & Fastenings** \_\_\_\_\_ **Timbers of the Frame at the Openings** \_\_\_\_\_  
**Lower Deck Beams & Fastenings** \_\_\_\_\_ **Ditto ditto at other places** \_\_\_\_\_  
**Planksheers** \_\_\_\_\_ **Keelsons** \_\_\_\_\_  
**Sheerstrakes** \_\_\_\_\_ **Clamps and Shelves** \_\_\_\_\_  
**Topsides** \_\_\_\_\_ **Ceiling** \_\_\_\_\_  
**Wales** \_\_\_\_\_ **Rudder** \_\_\_\_\_  
**Plank (Bottom) and Counter** \_\_\_\_\_ **Copper or Y.M.** \_\_\_\_\_ **When put on** \_\_\_\_\_  
**Engine Room Skylights** \_\_\_\_\_ **Coal Bunkers, Openings, Lids, &c.** \_\_\_\_\_ **Scuppers** \_\_\_\_\_ **Cargo and Main Hatchways** \_\_\_\_\_ **Hatches** \_\_\_\_\_  
**General Observations, Opinion as to Class, &c.** \_\_\_\_\_

**Committee's Minute** \_\_\_\_\_ **18** \_\_\_\_\_  
**Character assigned** \_\_\_\_\_



LON666-0006

The Surveyors are requested to insert Character precisely as in Register Book.

The Surveyors are requested to insert Character precisely as in Register Book.

The Surveyors are requested to insert Character precisely as in Register Book.