

ANNUAL SURVEYS.

*40513
5-11-81

No. _____ Survey held at London Date, first Survey 31st Oct. Last Survey 1st Nov. 18 81
No. in on the S.S. "Harter" Master F. Grandin
Reg. Book. 135 Net 1196 Built at Stockton When built 1844 2
Tonnage Gross 1844 Under Dk. 1482 By whom built Richardson & Duck Owners Shaw, Bushby & Co.
Port belonging to London Destined Voyage Japan via Middlesbrough
If Surveyed Afloat or in Dry Dock Lincolns Dry Dock (State Name of Dock.)

Last Survey, No. 40517 Port of Lon Classed _____ Years assigned. _____ Character in Register Book. 100 A. 1.
10-80

Present Condition of the
Decks Good Treenails Rivets Good
Waterways do Breasthooks and Stemson do
Comings do Transoms, Pointers, and Crutches do
Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
Lower Deck Beams & Fastenings do Ditto ditto at other places do
Planksheers do Keelsons do
Sheerstrakes do Clamps and Shelves do
Topsides do Ceiling do
Wales do Rudder do
Plank (Bottom) and Counter do Copper or Y.M. _____ When put on _____
Caulking of Bottom, Deck, & Waterways Good
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers do Cargo and Main Hatchways Good Hatches do
(If a Steam Ship, state if a Report is also sent on the Machinery do 10/11)
General Observations, Opinion as to Class, &c.

Bottom cleaned and coated, and some rivets in lower part of stern post renewed.
This vessel is in good condition and eligible to remain as classed.

Committee's Minute Friday, November, 11th 1881.

Character assigned 100A Joseph Thomson
Thos. Congdon Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____

No. in on the _____ Master _____
Reg. Book. _____ Year. _____ Month. _____
Tonnage { Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____ Years assigned. _____ Character in Register Book. _____

Present Condition of the
Decks _____ Treenails _____
Waterways _____ Breasthooks and Stemson _____
Comings _____ Transoms, Pointers, and Crutches _____
Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
Planksheers _____ Keelsons _____
Sheerstrakes _____ Clamps and Shelves _____
Topsides _____ Ceiling _____
Wales _____ Rudder _____
Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
Caulking of Bottom, Deck, & Waterways _____
Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
(If a Steam Ship, state if a Report is also sent on the Machinery _____)
General Observations, Opinion as to Class, &c.

Committee's Minute _____ 18 _____

Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____