

ANNUAL SURVEYS.

40504

No. Survey held at London Date, first Survey May 11th Last Survey June 7th 1881
 No. in on the SS Drummond Castle Master A Manchester
 Reg. Book. 22 Supp. Net 288 Built at Glasgow When built 1881 Month. 2
 Tonnage Gross 3705 By whom built Elder Owners J Currie
 Under Dk. 587 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Thames from Wks by St & Afloat
 (State Name of Dock.)

Last Survey, No. 5344 Port of Gls

Classed 100A 4.81.

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 (If a Steam Ship, state if a Report is also sent on the Machinery No)
 General Observations, Opinion as to Class, &c. Bottom to be coated.

She is now in an efficient state and eligible to remain as classed.

Committee's Minute

Friday, June, 11th 1881.

Senhouse Martindale

Character assigned

100A

TRM

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No.

Port of

Classed

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute


18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON666-0009



© 2021

Lloyd's Register Foundation