

ANNUAL SURVEYS.

40514

No. Survey held at London Date, first Survey May 13th Last Survey June 10th 1881
(Received at London Office, 13. 6. 81.)
 No. in on the 5 Orthes Master P Macfarlane
 Reg. Book. 278 Net 1206 Built at Glasgow When built 1877 11
 Tonnage Gross 1270 By whom built Thomson Owners A Russell
 Under Dk. 1133 Port belonging to Glasgow Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Greens by Sk & afloat
(State Name of Dock.)

Insert Character precisely as in Register Book.

Last Survey, No. 27416 Port of Iron Classed 100A 7.80
Years assigned. Character in Register Book.

Present Condition of the Decks	<u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Condition, how ascertained	<u>From Sk</u>
Planksheers	"	Keelsons	"	Sails	<u>good</u>
Sheerstrakes	"	Clamps and Shelves	"	Anchors, No. of <u>3 Bns. Sk & Pedgs</u>	<u>good</u>
Topsides	"	Ceiling	"	Cables <u>Parten Sk</u>	<u>good</u>
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	<u>Copper or Y.M. coated</u> When put on <u>now</u>	"	Standing and Running Rigging	"
Engine Room Skylights	"	Caulking of Bottom, Deck, & Waterways	<u>good</u>	Cargo and Main Hatchways	<u>good</u>
Coal Bunkers, Openings, Lids, &c.	"	Scuppers	<u>good</u>	Hatches	"
General Observations, Opinion as to Class, &c.	<u>Bottom to be coated</u>				

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, June, 14th 1881. Senhouse Martindale
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) TRW Paid 18

No. Survey held at London Date, first Survey May 17th Last Survey May 31st 1881
 No. in on the 5 Sydney Sacre Master R Jackson
 Reg. Book. 1328 Net 1205 Built at Stockton When built 1864 8
 Tonnage Gross 1386 By whom built Richardson Owners E Bates & Son
 Under Dk. 1256 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock James Sk by Sk & afloat
(State Name of Dock.)

Insert Character precisely as in Register Book.

Last Survey, No. 27218 Port of Iron Classed A 6.80
Years assigned. Character in Register Book.

Present Condition of the Decks	<u>good</u>	Treenails <u>Rivets</u>	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Condition, how ascertained	<u>From Sk</u>
Planksheers	"	Keelsons	"	Sails	<u>good</u>
Sheerstrakes	"	Clamps and Shelves	"	Anchors, No. of <u>3 Bns. Sk & Pedgs</u>	<u>good</u>
Topsides	"	Ceiling	"	Cables <u>Parten Sk</u>	<u>good</u>
Wales	"	Rudder	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	<u>Copper or Y.M. coated</u> When put on <u>now</u>	"	Standing and Running Rigging	"
Engine Room Skylights	"	Caulking of Bottom, Deck, & Waterways	<u>good</u>	Cargo and Main Hatchways	<u>good</u>
Coal Bunkers, Openings, Lids, &c.	"	Scuppers	<u>good</u>	Hatches	"
General Observations, Opinion as to Class, &c.	<u>Bottom to be coated</u>				

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Tuesday, June, 14th 1881. Senhouse Martindale
 Character assigned TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) TRW Paid 18

Insert Character precisely as in Register Book.

