

# ANNUAL SURVEYS.

40524

No. 1024 Survey held at London Date, first Survey 25 May Last Survey 13 June 18 81  
 No. in on the S. "Star of Germany" Master Wilson  
 Reg. Book. 1024 Tonnage { Net 1284 Built at Belfast When built 1870 3  
 Gross 1337 By whom built Holland Owners J. Curry & Co  
 Under Dk. 1216 Port belonging to Belfast Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock Canal dry dock (State Name of Dock.)

Last Survey, No. 26010 Port of Iron Classed 100 A 1 3.80  
 Present Condition of the Decks Good Treenails Good  
 Waterways do Breasthooks and Stemson do Windlass and Capstan Good  
 Comings do Transoms, Pointers, and Crutches do Pumps two do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do Boats four do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do Masts, Yards, &c. do  
 Planksheers do Keelsons do Condition, how ascertained from deck  
 Sheerstrakes do Clamps and Shelves do Sails well found  
 Topsides do Ceiling do Anchors, No. of 3 1/2 15 & 16  
 Wales do Rudder do Cables complete  
 Plank (Bottom) and Counter do Copper or Y.M. r When put on r Hawser and Warps sufficient  
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways do Standing and Running Rigging good  
 Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do

General Observations, Opinion as to Class, &c. Bottom cleaned and recoated. Fore topmast renewed. This ship appears eligible to remain as classed. Landed with ballast in main hold.  
 Committee's Minute Friday, June, 17th 1881. W. L. Longdon  
 Character assigned 100 A 1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No.          Survey held at          Date, first Survey          Last Survey          18           
 No. in on the          Master           
 Reg. Book.          Year.          Month.           
 Tonnage { Net          Built at          When built           
 Gross          By whom built          Owners           
 Under Dk.          Port belonging to          Destined Voyage           
 If Surveyed Afloat or in Dry Dock          (State Name of Dock.)

Last Survey, No.          Port of          Classed           
 Present Condition of the Decks          Treenails           
 Waterways          Breasthooks and Stemson          Windlass and Capstan           
 Comings          Transoms, Pointers, and Crutches          Pumps           
 Upper Deck Beams & Fastenings          Timbers of the Frame at the Openings          Boats           
 Lower Deck Beams & Fastenings          Ditto ditto at other places          Masts, Yards, &c.           
 Planksheers          Keelsons          Condition, how ascertained           
 Sheerstrakes          Clamps and Shelves          Sails           
 Topsides          Ceiling          Anchors, No. of           
 Wales          Rudder          Cables           
 Plank (Bottom) and Counter          Copper or Y.M.          When put on          Hawser and Warps           
 Engine Room Skylights          Caulking of Bottom, Deck, & Waterways          Standing and Running Rigging           
 Coal Bunkers, Openings, Lids, &c.          Scuppers          Cargo and Main Hatchways          Hatches         

General Observations, Opinion as to Class, &c.           
 Committee's Minute          18           
 Character assigned          Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18