

ANNUAL SURVEYS.

40534

No. 20 Survey held at London Date, first Survey 7 Last Survey 10 June 1887
 No. in on the Reg. Book. 20 " Pactolus " Master J. Rosser
 Tonnage { Net 397 Built at Pallion When built 1864 Month 6
 { Gross 416 By whom built Gill Owners Boadington & Co.
 { Under Dk. 395 Port belonging to London Destined Voyage Not fixed
 If Surveyed Afloat or in Dry Dock Buoys West Dock
(State Name of Dock.)

Last Survey, No. 38613 Port of Lon Classed 11A 10.79
 Present Condition of the Decks Good Treenails Good Cont. Lon June 75.7
 Waterways --- Breasthooks and Stemson --- HT Lon 79
 Comings --- Transoms, Pointers, and Crutches --- Windlass and Capstan Good
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings --- Pumps 2 No
 Lower Deck Beams & Fastenings --- Ditto ditto at other places Not seen Boats 3 No
 Planksheers --- Keelsons Good Masts, Yards, &c. ---
 Sheerstrakes --- Clamps and Shelves --- Condition, how ascertained from deck
 Topsides --- Ceiling --- Sails Good
 Wales --- Rudder --- Anchors, No. of 3 B. 15 & 2 K
 Plank (Bottom) and Counter Not seen Copper or Y.M. n f When put on 1879 Cables part seen Good
 Engine Room Skylights --- Coal Bunkers, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good
(If a Steam Ship, state if a Report is also sent on the Machinery.....)
 General Observations, Opinion as to Class, &c.
She appears where seen in good condition and
eligible to continue as classed

Committee's Minute Tuesday, June, 21st 1881. W. Head
 Character assigned Good Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 90 Survey held at London Date, first Survey 8 Last Survey 17th June 1881
 No. in on the Reg. Book. 90 " St. Ebenezer " Master J. Goodman
 Tonnage { Net 96 Built at Portmadoc When built 1858 Month ---
 { Gross 105 By whom built --- Owners P. Jones & Co.
 { Under Dk. 105 Port belonging to Cameroon Destined Voyage ---
 If Surveyed Afloat or in Dry Dock Survey Commercial St.
(State Name of Dock.)

Last Survey, No. 1944 Port of Pmd Classed 12 A 1
 Present Condition of the Decks Good Treenails Good Cont. Lon: 8 yrs.
 Waterways --- Breasthooks and Stemson --- S.S. 79-A1 in red 4 yrs - 5.79
 Comings --- Transoms, Pointers, and Crutches --- Windlass and Capstan Good
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings --- Pumps 2 No.
 Lower Deck Beams & Fastenings --- Ditto ditto at other places Not seen Boats 1 "
 Planksheers --- Keelsons Good Masts, Yards, &c. ---
 Sheerstrakes --- Clamps and Shelves --- Condition, how ascertained from deck
 Topsides --- Ceiling --- Sails sent new Good
 Wales --- Rudder Good where seen Anchors, No. of 2 B. 15 & 1 K
 Plank (Bottom) and Counter Not seen Copper or Y.M. --- When put on --- Cables Complete
 Engine Room Skylights --- Coal Bunkers, Openings, Lids, &c. --- Scuppers Good Cargo and Main Hatchways Good Hatches Good
(If a Steam Ship, state if a Report is also sent on the Machinery.....)
 General Observations, Opinion as to Class, &c.
She appears where seen to be in good condition &
eligible to remain as classed

Committee's Minute Tuesday, June, 21st 1881. W. Head
 Character assigned Good Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.



LON 666-0084