

ANNUAL SURVEYS.

* 40535

22/11/81

No. Survey held at London Date, first Survey Oct 24 Last Survey Oct 26 1881
 No. in on the Screw Steamer Dorunda Master Templeton
 Reg. Book 385 Tonnage 1943 Built at Dumbarton When built 1875 - 10 Mo
 By whom built W. Denny & Brothers Owners D. Macneil & P. Denny
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock

Last Survey, No. 40503 Port of London Classed 100 A 1
 Present Condition of the Decks Good Transoms Rivets Good S.S. Low No 1-79 6, 81
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Members of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Rudder "
Copper or V.M. Cemented When put on 1875
 Caulking of Good
 Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained by observation
 Sails Sufficient
 Anchors, No. of 3 B, 1 L & 2 K
 Cables part seen on deck good
 Hawser and Warps Sufficient
 Standing and Running Rigging "

Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scupper's Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Several butts recaulked at the bilges, a few rivets in the rudder braces renewed also 3 planks in the deck on S^d side and the bottom recoated with Paint.
This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.
 Committee's Minute Friday, Nov 6th, 25th 1881.
 Character assigned 100 A 1
B 3. 11.11.1881

Lloyd's Register
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 5/ Paid 5/12 1881 B

1800-292007