

# ANNUAL SURVEYS.

40566

(Received at London Office, 27<sup>th</sup> 81)

No. 350 Survey held at London Date, first Survey 13 June Last Survey 13 June 1881  
 on the "S. S. Sinaru" Master Fulbertson  
 Reg. Book. 350 Net 1306 Built at Greenock When built 1874 12 Month.  
 Tonnage Gross 1363 By whom built Scott Owners Albion S. Coe  
 Under Dk. 1164 Port belonging to Glasgow Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Ruggs dry dock  
(State Name of Dock.)

Last Survey, No. 39425 Port of London Classed 100A/1 7.80  
Years assigned. Character in Register Book.

Present Condition of the Decks <u>Good</u>	Treenails <u>Roets</u>	Rods <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Windlass and Capstan <u>Good</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Pumps <u>two</u> <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Boats <u>four</u> <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Masts, Yards, &c. <u>do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Condition, how ascertained <u>per deck</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Sails <u>well found</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Anchors, No. of <u>30. 15 &amp; 10</u>
Wales <u>do</u>	Rudder <u>do</u>	Cables <u>complete</u>
Plank (Bottom) and Counter <u>do</u>	Copper or Y.M. <u>do</u> When put on <u>do</u>	Hawsers and Warps <u>sufficient</u>
Engine Room Skylights <u>do</u>	Caulking of Bottom, Deck, & Waterways <u>do</u>	Standing and Running Rigging <u>good</u>
Coal Bunkers, Openings, Lids, &c. <u>do</u>	Scuppers <u>do</u>	Cargo and Main Hatchways <u>do</u> Hatches <u>do</u>

General Observations, Opinion as to Class, &c.  
Bottom cleaned and re-coated. This vessel appears eligible to remain as classed.  
Surveyed with ballast in the hold.

Committee's Minute Tuesday, July, 5th 1881. Wm. Longdon  
 Character assigned 100A/1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 470 Survey held at London Date, first Survey 20 June Last Survey 29 June 1881  
 on the "Pleiades" Master Letten  
 Reg. Book. 470 Net 997 Built at Dumbarton When built 1869 4 Month.  
 Tonnage Gross 1020 By whom built McWilliam Owners Shaw Saville & Coe  
 Under Dk. 925 Port belonging to Southampton Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock do  
(State Name of Dock.)

Last Survey, No. 27423 Port of London Classed X/D/1 7.80  
Years assigned. Character in Register Book.


Present Condition of the Decks <u>Good</u>	Treenails <u>Roets</u>	Rods <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Windlass and Capstan <u>Good</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Pumps <u>two</u> <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the Openings <u>do</u>	Boats <u>four</u> <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto ditto at other places <u>do</u>	Masts, Yards, &c. <u>do</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Condition, how ascertained <u>per deck</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Sails <u>well found</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Anchors, No. of <u>30. 15 &amp; 10</u>
Wales <u>do</u>	Rudder <u>do</u>	Cables <u>complete</u>
Plank (Bottom) and Counter <u>do</u>	Copper or Y.M. <u>do</u> When put on <u>do</u>	Hawsers and Warps <u>sufficient</u>
Engine Room Skylights <u>do</u>	Caulking of Bottom, Deck, & Waterways <u>do</u>	Standing and Running Rigging <u>good</u>
Coal Bunkers, Openings, Lids, &c. <u>do</u>	Scuppers <u>do</u>	Cargo and Main Hatchways <u>do</u> Hatches <u>do</u>

General Observations, Opinion as to Class, &c.  
Bottom cleaned and re-coated. This vessel appears eligible to remain as classed.

Committee's Minute Tuesday, July, 5th 1881. Wm. Longdon  
 Character assigned 100A/1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

Annual Survey, when there are no repairs, 4000-612/80. Inserted not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.



LONG666-0165

Lincoln  
&  
Pleates



© 2021

Lloyd's Register  
Foundation

ANNOTS SUBVARS