

ANNUAL SURVEYS.

40566

No. *15481* Survey held at *London* Date, first Survey *Nov 10th* Last Survey *Nov 11th* 1881
 No. in on the *SS* *Glencoe* Master *W Gulland*
 Reg. Book. *445* Net *1901* Built at *Glasgow* When built *1878* 11
 Tonnage Gross *2913* Under Dk. *2685* By whom built *Sen & Glas Co* Owners *M Gregor Gow & Co*
 Port belonging to *Glasgow* Destined Voyage *China*
 If Surveyed Afloat or in Dry Dock *Green by St*
(State Name of Dock.)

Last Survey, No. *40034* Port of *Lon* Classed *100 A 1.81*
Years assigned. Character in Register Book.

Present Condition of the
 Decks *Good* Treenails *Rivets* *Good*
 Waterways *"* Breasthooks and Stenson *"*
 Comings *"* Transoms, Pointers, and Crutches *"* Windlass and Capstan *Good*
 Upper Deck Beams & Fastenings *"* Timbers of the Frame at the Openings *"* Pumps *"*
 Lower Deck Beams & Fastenings *"* Ditto ditto at other places *"* Boats *"*
 Planksheers *"* Keelsons *"* Masts, Yards, &c. *"*
 Sheerstrakes *"* Clamps and Shelves *"* Condition, how ascertained *From St*
 Sides *"* Ceiling *"* Sails *Good*
 es *"* Rudder *"* Anchors, No. of *3 Bra St & Kelly*
 k (Bottom) and Counter *"* Copper or Y.M. *Copper* When put on *now* Cables *Park on St* *Good*
 Caulking of Bottom, Deck, & Waterways *Good* Standing and Running Rigging *"*
 e Room Skylights *Good* Coal Bunkers, Openings, Lids, &c. *Good* Scuppers *Good* Cargo and Main Hatchways *Good* Hatches *"*

General Observations, Opinion as to Class, &c. *Bottom & counter*
She is now in an efficient state and eligible to remain as classed

Senhouse Martindale

Committee's Minute *Friday, December, 2nd, 1881*
 Character assigned *100 A 1*
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 in on the _____ Master _____
 Book. _____ Year. _____ Month. _____
 Tonnage Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Destined Voyage _____
 Port belonging to _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Condition of the
 rways _____ Treenails _____
 ngs _____ Breasthooks and Stenson _____
 Upper Deck Beams & Fastenings _____ Transoms, Pointers, and Crutches _____
 Lower Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Planksheers _____ Ditto ditto at other places _____
 Sheerstrakes _____ Keelsons _____
 Topsides _____ Clamps and Shelves _____
 Wales _____ Ceiling _____
 Plank (Bottom) and Counter _____ Rudder _____
 Copper or Y.M. _____ When put on _____
 Caulking of Bottom, Deck, & Waterways _____
 e Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 Steam Ship, state if a Report is also sent on the Machinery _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____