

# ANNUAL SURVEYS.

No.            Survey held at London. Date, first Survey 16<sup>th</sup> May Last Survey 2<sup>nd</sup> July 1881  
No. in on the Iron S. "Collingwood" Master A. N. Forbes.  
Reg. Book. 1039 Net 1011 Built at Aberdeen. When built 1872 6<sup>th</sup> Month.  
1038 Tonnage Gross 1064 By whom built Hood Owners Devitt & Moore  
Under Dk. 945 Port belonging to London. Destined Voyage Melbourne  
If Surveyed Afloat or in Dry Dock In Nelson Dry Dock.  
(State Name of Dock.)

Last Survey, No. 27494 Port of Iron Classed S.S. Lon. No 2-80. Years assigned. 100 A. 1. Character in Register Book. 7.80  
Present Condition of the  
Decks good Treennails good Rivets good  
Waterways D<sup>o</sup> Breasthooks and Stemson D<sup>o</sup>  
Comings D<sup>o</sup> Transoms, Pointers, and Crutches D<sup>o</sup>  
Upper Deck Beams & Fastenings D<sup>o</sup> Timbers of the Frame at the Openings D<sup>o</sup>  
Lower Deck Beams & Fastenings D<sup>o</sup> Ditto ditto at other places D<sup>o</sup>  
Planksheers D<sup>o</sup> Keelsons D<sup>o</sup>  
Sheerstrakes D<sup>o</sup> Clamps and Shells D<sup>o</sup>  
Topsides D<sup>o</sup> Ceiling D<sup>o</sup>  
Wales D<sup>o</sup> Rudder D<sup>o</sup>  
Plank (Bottom) and Counter D<sup>o</sup> Copper or Y.M.            When put on             
Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers good Cargo and Main Hatchways good Hatches good  
(If a Steam Ship, state if a Report is also sent on the Machinery           )  
General Observations, Opinion as to Class, &c. Vessel surveyed with part outward cargo & some ballast in the hold.  
The bottom has been examined, cleaned and coated, some of the rudder pintles  
rebushed. One deck plank renewed on the port side forward.  
This vessel appears to be in good and efficient condition and eligible to remain  
as classed.

Committee's Minute Friday, July, 8th 1881. J. H. Truscott.  
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18

No.            Survey held at            Date, first Survey            Last Survey            18            
No. in on the            Master             
Reg. Book.            Net            Built at            When built            Year.            Month.             
Tonnage Gross            By whom built            Owners             
Under Dk.            Port belonging to            Destined Voyage             
If Surveyed Afloat or in Dry Dock             
(State Name of Dock.)  
Last Survey, No.            Port of            Classed            Years assigned.            Character in Register Book.             
Present Condition of the  
Decks            Treennails             
Waterways            Breasthooks and Stemson             
Comings            Transoms, Pointers, and Crutches             
Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
Lower Deck Beams & Fastenings            Ditto ditto at other places             
Planksheers            Keelsons             
Sheerstrakes            Clamps and Shells             
Topsides            Ceiling             
Wales            Rudder             
Plank (Bottom) and Counter            Copper or Y.M.            When put on             
Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
(If a Steam Ship, state if a Report is also sent on the Machinery           )  
General Observations, Opinion as to Class, &c.           

Committee's Minute 18  
Character assigned           

Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18

LON666-0182