

ANNUAL SURVEYS.

40595
5.7.81

No. _____ Survey held at London Date, first Survey 30 June Last Survey July 1887
 No. in on the Iron S.S. "London" Master Norris
 Reg. Book 655 Year. _____ Month. _____
 Tonnage { Net 831 Built at Newcastle When built 1862 3
 Gross 1325 By whom built Leslie Owners J. Hall & Co
 Under Dk. 854 Port belonging to London Destined Voyage Ladyg
 If Surveyed Afloat or in Dry Dock Leithhouse dry Dock
(State Name of Dock.)

Last Survey, No. from Port of 27988 Classed 100A1 7-79
 Present Condition of the Decks Good Treenails Good Breasthooks and Stemson Good
 Waterways _____ Transoms, Pointers, and Crutches _____ Windlass and Capstan Good
 Comings _____ Timbers of the Frame at the Openings _____ Pumps _____
 Upper Deck Beams & Fastenings _____ Ditto ditto at other places _____ Boats _____
 Lower Deck Beams & Fastenings _____ Keelsons _____ Masts, Yards, &c. _____
 Planksheers _____ Clamps and Shelves _____ Condition, how ascertained from Deck
 Sheerstrakes _____ Ceiling _____ Sails Good
 Topsides _____ Rudder _____ Anchors, No. of 3 B. 15 + 2 K
 Wales _____ Copper or Y.M. Cement When put on Feb 82 Cables 300 fms Good
 Plank (Bottom) and Counter _____ Caulking of Bottom, Deck, & Waterways Good Hawsers and Warps 5 no
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
(If a Steam Ship, state if a Report is also sent on the Machinery.....)


General Observations, Opinion as to Class, &c. Bottom cleared and recoated. She is now in good condition and eligible in my opinion to continue reclassified

Committee's Minute _____ Friday, July, 15th 1881 W. L. Davey
 Character assigned B.S. 7. 81 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 No. in on the _____ Master _____ Year. _____ Month. _____
 Reg. Book _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____
 Waterways _____ Breasthooks and Stemson _____ Windlass and Capstan _____
 Comings _____ Transoms, Pointers, and Crutches _____ Pumps _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ Boats _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ Masts, Yards, &c. _____
 Planksheers _____ Keelsons _____ Condition, how ascertained _____
 Sheerstrakes _____ Clamps and Shelves _____ Sails _____
 Topsides _____ Ceiling _____ Anchors, No. of _____
 Wales _____ Rudder _____ Cables _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____ Hawsers and Warps _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
(If a Steam Ship, state if a Report is also sent on the Machinery.....)

Committee's Minute _____ 18 _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18



Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

LON666-0240