

ANNUAL SURVEYS.

40599

No. Survey held at London Date, first Survey and Last Survey 25 June 1881
 No. in on the Gen S.S. "Malaya" Master J. Russell
 Reg. Book. 166 Net 1024 Built at Hartlepool When built 1876 Year. 4 Month.
 Tonnage { Gross 1614 By whom built Gay Owners J. Hall & Co
 Under Dk. 1420 Port belonging to London Destined Voyage Lady
 If Surveyed Afloat or in Dry Dock Union Dock (State Name of Dock.)

Last Survey, No. 26951 Port of Gen Classed 100 A 1 6 80
 S.S. No 1.80

Present Condition of the Decks Good Treenails Rivets Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places Not seen
 Planksheers Keelsons Good
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Lead When put on 76
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 If a Steam Ship, state if a Report is also sent on the Machinery
 General Observations, Opinion as to Class, &c.

Bottom repaired. She is now in good condition and in my opinion is eligible to continue as classed

Committee's Minute Friday, July, 15th 1881. Wm. B. Davy
 Character assigned 100 A 1 6 80 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage { Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed
 Years assigned. Character in Register Book.

Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 If a Steam Ship, state if a Report is also sent on the Machinery
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



Insert Character precisely as in Register Book.

8420-999N07