

# REPORT of SURVEY for REPAIRS, &c.

No. 207 on the S The Lord Warden Date, first Survey May 18 Last Survey July 12<sup>th</sup> 18 81  
 No. in Survey held at London (Received at London Office, 19.7.81)  
 eg. Book. 207 Master Cooke  
 TONNAGE under Tonnage Deck 1081 Built at Sunderland When built 1862 YEAR. MONTH.  
 Ditto of Spar Deck, or Avning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 1237 Owners R & H Green Port belonging to London  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam 1237 Residence  
 Engine Room By whom built Pile Destined Voyage Australia  
 Reg. Tons as St<sup>r</sup>mer, cut on Bm. If Surveyed Afloat or in Dry Dock Greens Dry Dock  
 (State Name of Dock)  
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.  
 Last Survey, No. 39520 Port Lon Classed 15th 8.80  
 REPAIRS, OR EXAMINATION AS PER RULE  
 Cause of Repairs to be clearly stated.

At the present time the repair placed in the dry dock the yellow metal stripped off baulked from keel to above the load line and reyellow metalled on keel to load line.

| Present Condition of the                       |             |  |                |
|--|-------------|--|----------------|
| Decks  | <u>Good</u> | Treenails  | <u>Good</u>    |
| Waterways                                      | <u>"</u>    | Breasthooks and Stemson                            | <u>"</u>       |
| Comings  | <u>"</u>    | Transoms, Pointers, and Crutches                   | <u>"</u>       |
| Upper Deck Beams & Fastenings                  | <u>"</u>    | Timbers of the Frame at the openings               | <u>"</u>       |
| Lower Deck Beams & Fastenings                  | <u>"</u>    | Ditto Ditto at other places                        | <u>"</u>       |
| Planksheers                                    | <u>"</u>    | Keelsons   | <u>"</u>       |
| Sheerstrakes                                   | <u>"</u>    | Clamps and Shelves                                 | <u>"</u>       |
| Topsides                                       | <u>"</u>    | Ceiling  | <u>"</u>       |
| Wales  | <u>"</u>    | Rudder   | <u>"</u>       |
| Plank (Bottom) and Counter                     | <u>"</u>    | Copper (on Y.M.) <u>When put on new</u>            | <u>"</u>       |
| Engine Room Skylights                          | <u>"</u>    | Caulking of  | <u>"</u>       |
| Coal Bunker, Openings, Lids, &c.               | <u>"</u>    | Bottom, Deck, & Waterways                          | <u>Good</u>    |
| General Observations, Opinion as to Class, &c. |             |  |                |
|  |             | Scuppers   | <u>Good</u>    |
|  |             | Cargo and Main Hatchways                           | <u>Good</u>    |
|  |             | Hatches  | <u>"</u>       |
|  |             | Windlass and Capstan                               | <u>Good</u>    |
|  |             | Pumps  | <u>"</u>       |
|  |             | Boats  | <u>"</u>       |
|  |             | Masts, Yards, &c.                                  | <u>"</u>       |
|  |             | Condition, how ascertained                         | <u>From Bk</u> |
|  |             | Sails  | <u>Good</u>    |
|  |             | Anchors No. of <u>3</u> Buo. <u>SE &amp; Redys</u> | <u>"</u>       |
|  |             | Cables <u>Part on Bk</u>                           | <u>Good</u>    |
|  |             | Hawsers and Warps                                  | <u>"</u>       |
|  |             | Standing & Running Rigging                         | <u>"</u>       |

She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

The Amount of Entry Fee ... £ 2 : 2 : 0 received by me, C. J. R.  
 Special ... £ 2 : 2 : 0 18 81  
 Certificate (if required) to be sent as per margin... £ 5 : 0 : 0  
 (Travelling Expenses, if any, £ 0 : 0 : 0)  
 Committee's Minute Friday, July, 22nd 18 81.  
 Character assigned Class 10A



© 2021

Lloyd's Register  
Foundation