

187/89

ANNUAL SURVEYS.

40636

No. 184 Survey held at London Date, first Survey July 22 Last Survey July 4 1881
No. in on the SS Thames Master Simpson
Reg. Book. 1057 Tonnage 1687 Built at Dumbarton When built 1871-3
By whom built W. Millan Owners Temperley Carter & Satchell
Port belonging to London Destined Voyage Montreal
If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock

Last Survey, No. 25319 Port of Iron Classed 100A 1275
Present Condition of the Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Copper When put on now
Engine Room Skylights " Caulking of Bottom, Deck, & Waterways Good
Coal Bunker, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
General Observations, Opinion as to Class, &c. Bottom in contact

She is now in an efficient state
and eligible to remain as classed.
(one indented lapside plate failed & rivetted.)

Committee's Minute Sanhouse Martindale
Tuesday, July, 26th 1881.
Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) TRW Paid 18

No. 18 Survey held at 18 Date, first Survey 18 Last Survey 18
No. in on the 18 Master 18
Reg. Book. 18 Tonnage 18 Built at 18 When built 18
By whom built 18 Owners 18
Port belonging to 18 Destined Voyage 18
If Surveyed Afloat or in Dry Dock 18

Last Survey, No. 18 Port of 18 Classed 18
Present Condition of the Decks 18 Treenails 18
Waterways 18 Breasthooks and Stemson 18
Comings 18 Transoms, Pointers, and Crutches 18
Upper Deck Beams & Fastenings 18 Timbers of the Frame at the Openings 18
Lower Deck Beams & Fastenings 18 Ditto ditto at other places 18
Planksheers 18 Keelsons 18
Sheerstrakes 18 Clamps and Shelves 18
Topsides 18 Ceiling 18
Wales 18 Rudder 18
Plank (Bottom) and Counter 18 Copper or Y.M. 18 When put on 18
Engine Room Skylights 18 Caulking of Bottom, Deck, & Waterways 18
Coal Bunkers, Openings, Lids, &c. 18 Scuppers 18 Cargo and Main Hatchways 18 Hatches 18
General Observations, Opinion as to Class, &c. 18

Committee's Minute 18
Character assigned 18

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required) 18 Paid 18

