

ANNUAL SURVEYS.

40653

(Received at London Office, 16. 4. 7. 81)

No. _____ Survey held at London Date, first Survey 1st July Last Survey 5th July 1881
 No. in on the Iron Screw "Ceto." Master G. Tucker.
 Reg. Book. 518 Tonnage { Net 612 Built at Stockton When built 1878 1st
 { Gross 970 By whom built M. Pearse & Co Owners A. C. Coake.
 { Under Dk. 742 Port belonging to London. Destined Voyage Bermuda & Nassau.
 If Surveyed Afloat or in Dry Dock In the Bridge Dry Dock.
(State Name of Dock.)

Last Survey, No. 27365 Port of Iron Classed 100A.1.
Years assigned. 3.81 Character in Register Book.

Present Condition of the Decks <u>good</u> Waterways <u>D^o</u> Comings <u>D^o</u> Upper Deck Beams & Fastenings <u>D^o</u> Lower Deck Beams & Fastenings <u>D^o</u> Planksheers <u>D^o</u> Sheerstrakes <u>D^o</u> Topsides <u>D^o</u> Wales <u>D^o</u> Plating <u>D^o</u> Plank (Bottom) and Counter <u>D^o</u>	Treennails <u>good</u> Rivets <u>good</u> Breasthooks and Stenson <u>D^o</u> Transoms, Pointers, and Crutches <u>D^o</u> Timbers of the Frames at the Openings <u>D^o</u> Ditto ditto at other places <u>D^o</u> Keelsons <u>D^o</u> Clamps and Shelves <u>D^o</u> Ceiling <u>D^o</u> Rudder <u>D^o</u> Copper or Y.M. <u>When put on</u> Caulking of Bottom, Deck, & Waterways <u>good</u>	Windlass and Capstan <u>good</u> Pumps <u>D^o</u> Boats <u>D^o</u> Masts, Yards, &c. <u>D^o</u> Condition, how ascertained <u>from the deck</u> Sails <u>good</u> Anchors, No. of <u>3 B. 1 S. 2 K.</u> Cables <u>complete</u> Hawsers and Warps <u>sufficient</u> Standing and Running Rigging <u>good</u> Engine Room Skylights <u>good</u> Coal Bunkers, Openings, Lids, &c. <u>good</u> Scuppers <u>good</u> Cargo and Main Hatchways <u>good</u> Hatches <u>good</u> . (If a Steam Ship, state if a Report is also sent on the Machinery.....) General Observations, Opinion as to Class, &c. <u>The bottom has been coated. the rudder pintles bushed.</u> <u>She appears to be in good and efficient condition, and eligible to remain as classed.</u>
---	--	---


Committee's Minute Friday July, 29th 18 81. J. H. Truscott.
 Character assigned 100A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 1881

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Year. _____ Month. _____
 Tonnage { Net _____ Built at _____ When built _____
 { Gross _____ By whom built _____ Owners _____
 { Under Dk. _____ Destined Voyage _____
 Port belonging to _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. _____ Character in Register Book.

Present Condition of the Decks _____ Waterways _____ Comings _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Planksheers _____ Sheerstrakes _____ Topsides _____ Wales _____ Plank (Bottom) and Counter _____	Treennails _____ Rivets _____ Breasthooks and Stenson _____ Transoms, Pointers, and Crutches _____ Timbers of the Frame at the Openings _____ Ditto ditto at other places _____ Keelsons _____ Clamps and Shelves _____ Ceiling _____ Rudder _____ Copper or Y.M. _____ When put on _____ Caulking of Bottom, Deck, & Waterways _____	Windlass and Capstan _____ Pumps _____ Boats _____ Masts, Yards, &c. _____ Condition, how ascertained _____ Sails _____ Anchors, No. of _____ Cables _____ Hawsers and Warps _____ Standing and Running Rigging _____ Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____ (If a Steam Ship, state if a Report is also sent on the Machinery.....) General Observations, Opinion as to Class, &c.
--	--	--

Committee's Minute _____ 18 _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18 _____



Insert Character precisely as in Register Book.

LON 666-0319