

# ANNUAL SURVEYS.

No. 111 Survey held at London Date, first Survey June 16<sup>th</sup> Last Survey July 23<sup>rd</sup> 1881  
 No. in on the Reg. Book. SS Gauth Castle Master M. C. Webster  
 Tonnage { Net 2381 Built at Glasgow When built 1880 12  
 Gross 3705 By whom built J. Elder Owners S. Currie & Co  
 Under Dk. 3537 Port belonging to London Destined Voyage South to open New South  
 If Surveyed Afloat or in Dry Dock James Dun Walks Dry at Vastock  
 (State Name of Dock.)

Last Survey, No. 5306 Port of Glo. Classed 100A 2-81

Present Condition of the  
 Decks Good Treenails Revised Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on once  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 (If a Steam Ship, state if a Report is also sent on the Machinery.....)  
 General Observations, Opinion as to Class, &c. Bottom & coated. She is now in an efficient state and eligible to remain as classed

Committee's Minute Friday, July, 29<sup>th</sup> 18 81  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) PAID 1881

No.        Survey held at        Date, first Survey        Last Survey        18        
 No. in on the Reg. Book.        Master         
 Tonnage { Net        Built at        When built        12  
 Gross        By whom built        Owners         
 Under Dk.        Port belonging to        Destined Voyage         
 If Surveyed Afloat or in Dry Dock         
 (State Name of Dock.)

Last Survey, No.        Port of        Classed       

Present Condition of the  
 Decks        Treenails         
 Waterways        Breasthooks and Stemson         
 Comings        Transoms, Pointers, and Crutches         
 Upper Deck Beams & Fastenings        Timbers of the Frame at the Openings         
 Lower Deck Beams & Fastenings        Ditto ditto at other places         
 Planksheers        Keelsons         
 Sheerstrakes        Clamps and Shelves         
 Topsides        Ceiling         
 Wales        Rudder         
 Plank (Bottom) and Counter        Copper or Y.M.        When put on         
 Caulking of Bottom, Deck, & Waterways         
 Engine Room Skylights        Coal Bunkers, Openings, Lids, &c.        Scuppers        Cargo and Main Hatchways        Hatches         
 (If a Steam Ship, state if a Report is also sent on the Machinery.....)  
 General Observations, Opinion as to Class, &c.       

Committee's Minute 18  
 Character assigned        Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) PAID 18      

LON666-0327



*Handwritten notes and signatures at the top right of the page.*



© 2021

Lloyd's Register  
Foundation