

ANNUAL SURVEYS.

40673

No. 624 on the Rock Wren Survey held at London Date, first Survey 14 July Last Survey 14 July 1881
 Reg. Book. 624 Master Murdock
 Tonnage { Net 716 Built at P. Glasgow When built 1840
 Gross 821 By whom built Mc-Culloch Owners Spratt
 Under Dk. 696 Port belonging to Lpool Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Linehouse dry dock
 (State Name of Dock.)

Last Survey, No. 28088 Port of Iron Classed 100A
 Present Condition of the Decks Good Treenails Pinets Rood Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. When put on do
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do Cargo and Main Hatchways do Hatches do
 (If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.
Bottom cleaned and recoated. Rudder pintles knocked. This vessel appears eligible to remain as classed.

Surveyed with Cargo in the main hold
 Committee's Minute Friday, August, 5th 1881. Sub. Longdon
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 Reg. Book. Master
 Tonnage { Net Built at When built
 Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.

 Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Loch Ness



© 2021

Lloyd's Register
Foundation