

ANNUAL SURVEYS.

40674.

No. 152 Survey held at London Date, first Survey 28th June Last Survey 15 July 1881
No. in on the Bn "Zulu" Master R. Lewis
Reg. Book. 141 Tonnage { Net 280 Built at South Shields When built 1872 3rd Month
Gross 296 By whom built Wingo Owners Bullard, King & Co
Under Dk. 278 Port belonging to London Destined Voyage Natal
If Surveyed Afloat or in Dry Dock In the Lower Globe Dry Dock.
(State Name of Dock.)

Last Survey, No. 38110 Port of Lon
Present Condition of the
Decks good Treenails good
Waterways D^o Breasthooks and Stemson D^o
Comings D^o Transoms, Pointers, and Crutches D^o
Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
Lower Deck Beams & Fastenings D^o Ditto ditto at other places D^o
Planksheers D^o Keelsons D^o
Sheerstrakes D^o Clamps and Shelves D^o
Topsides D^o Ceiling D^o
Wales D^o Rudder D^o
Plank (Bottom) and Counter D^o Copper or Y.M. good When put on 79
Caulking of Bottom, Deck, & Waterways good
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good
(If a Steam Ship, state if a Report is also sent on the Machinery)

General Observations, Opinion as to Class, &c.
This vessel has been placed in dry dock; the bottom sighted & the yellow metal sheathing repaired. A few bolts in the hold beam hanging knees renewed of yellow metal. The hatches to the main hatchway renewed.
Vessel surveyed with part outward cargo in the hold amidships.
She appears to be in good and efficient condition and eligible to remain as classed.

Committee's Minute Friday, August, 5th 1881.
Character assigned 11A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in on the Master
Reg. Book. Year. Month.
Tonnage { Net Built at When built
Gross By whom built Owners
Under Dk. Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
nt Condition of the
Deck Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
(If a Steam Ship, state if a Report is also sent on the Machinery)

Committee's Minute 18
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18