

ANNUAL SURVEYS.

(Received at London Office, 6/8/81)

No. _____ Survey held at London Date, first Survey Aug 2^d Last Survey Aug 3^d 18 81
 No. in on the SS Dacia Master Hayward
 Reg. Book. _____ Built at Sunderland When built 1867 11
 Tonnage { Net 1473 Built at _____ When built _____
 Gross 1856 By whom built Sainy Owners In Pub. Int Per Telegraph
 Under Dk. 1252 Port belonging to London Destined Voyage not known
 If Surveyed Afloat or in Dry Dock James & W Dry St
(State Name of Dock.)

Last Survey, No. 28647 Port of London

Classed B1 1280
 SS London 12.80
 Character in Register Book.

Present Condition of the		
Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	<u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Canted</u>	When put on <u>Now</u>
Engine Room Skylights <u>Good</u>	Caulking of <u>Good</u>	Bottom, Deck, & Waterways <u>Good</u>
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Hatches <u>"</u>		

General Observations, Opinion as to Class, &c. Bottom &c canted
She is now in an efficient state and eligible to remain as classed.

Samhouse Martindale

Committee's Minute Tuesday, August, 9th 1881.

Character assigned B1 JRM Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) 5/- Paid 15/81 18 81

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____
 No. in on the _____ Master _____
 Reg. Book. _____ Built at _____ When built _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____

Classed _____
 Character in Register Book.

Present Condition of the		
Decks _____	Treenails _____	
Waterways _____	Breasthooks and Stemson _____	Windlass and Capstan _____
Comings _____	Transoms, Pointers, and Crutches _____	Pumps _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Boats _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Masts, Yards, &c. _____
Planksheers _____	Keelsons _____	Condition, how ascertained _____
Sheerstrakes _____	Clamps and Shelves _____	Sails _____
Topsides _____	Ceiling _____	Anchors, No. of _____
Wales _____	Rudder _____	Cables _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____	Hawsers and Warps _____
Engine Room Skylights _____	Caulking of _____	Standing and Running Rigging _____
Coal Bunkers, Openings, Lids, &c. _____	Bottom, Deck, & Waterways _____	Hatches _____
Scuppers _____ Cargo and Main Hatchways _____		

General Observations, Opinion as to Class, &c. _____

Committee's Minute 18

Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

Form No. 4 for Annual Surveys are requested not to write on or below the space for Committee's Minute.



LONG666-0355



© 2021

Lloyd's Register Foundation